## NSL NSL **BLACKWOOD & NICHOLS COMPANY**

by in , leaver mo. & water

Box 1237 DURANGO, COLORADO

Och ad by Emery 2/58) ( O.K. ed by Smery 2/58) per telephone m 5/2/58)

April 29, 1958

Mr. A. L. Porter, Jr. Secretary-Director Oil Conservation Commission P.O. Box 871 Santa Fe, New Mexico

Dear Mr. Porter:

As Operator of the Northeast Blanco Unit, we request permission to drill an unorthodox well, to be located 2230' from the North line and 1800<sup>t</sup> from the East line of Section 19, T 31 N, R 7 W, San Juan County, New Mexico. We want to drill Well No. 66-19 on this location.

Because of the extremely rough terrain in and surrounding the normal location for this well, it is necessary to select a more suitable drilling site.

Section 19-31N-7W is a part of the Northeast Blanco Unit and all leases within a 790' radius of the unorthodox location, as requested, is jointly controlled by the Northeast Blanco Unit participants.

We enclose a location plat of the requested location.

Very truly yours,

BLACKWOOD & NICHOLS COMPANY

DeLasso Loos, Field Superintendent

FW/bh Encl.

United States Geological Survey cc: Farmington, New Mexico

> Blackwood & Nichols Company Oklahoma City, Oklahoma

NEW MEXICO OIL CONSERVATION COMMISSION Revised 5/1/57 Well Location and Acreage Dedication Plat Date April 22, 1958 Section A. Operator BLACKWOOD & NICHOLS CO. Leese NORTHEAST BLANCO UNIT Well No. 65-19 Unit Letter G Section 19 Township 31 N Range 7 W NMPM Located 2230 Feet From northLine, County San Juan G. L. Elevation 1800 Feet From east Line Dedicated Acreage Acres Name of Producing Formation Mesa Verde Pool Blanco Mesa Verde 1. Is the Operator the only owner\* in the dedicated acreage outlined on the plat below? X Yes No If the angwer to question one is "no", have the interests of all the owners been 2. consolidated by communitization agreement or otherwise? Yes x No . If answer is Unitization "yes", Type of Consolidation 3. If the answer to question two is "no", list all the owners and their respective interests below: Land Description Owner Section B This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief. Blackwood & Nichols Company (Operator) ---- Délasso Loos Deep Conyon (Representative) Field Superintendent 1800 P.O. Box 1237, Durango, Colorado Address This is to certify that the well location shown on the plet in Section B was plotted from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and 3100 belief. Surveyed April 22, 1958 Date mun John A. Kroeger Registered Land Surveyor Durango, Colorado

330 660 990 1320 1650 1980 2310 2640 2000 1500 500 Certificate No. 1941

Form C-128