District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

x Initial Report ☐ Final Report

Name of Company Plains Pipeline	Contact Camille Reynolds
Address 3112 W. US Hwy 82, Lovington, NM 88260	Telephone No. 505-441-0965
Facility Name E.K. Queen 6 Inch State	Facility Type 6"Steel Pipeline

Surface Owner SLO	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	20	18S	34E					Lea

GW~98'

Latitude 32° 44' 12.4" **Longitude** 103° 34' 41.5"

NATURE OF RELEASE

Type of ~~Release Crude~~ Oil	Volume of Release 20 barrels	Volume Recovered 0 barrels
Source of Release 6" Steel Pipeline	Date and Hour of Occurrence 02/02/2007 @ 10:45	Date and Hour of Discovery 02/02/2007 @ 11:00
Was Immediate Notice Given? X Yes ☐ No ☐ Not Required	If YES, To Whom? Pat Caperton	
By Whom? Camille Reynolds	Date and Hour 02/02/2007 @ 14:33	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken Internal corrosion of the 6 inch steel pipeline resulted in release of sweet crude oil. The line is a 6-inch steel gathering line that produces approximately 433 barrels of oil per day. The pressure on the line is approximately 150 psi and the gravity of the sweet crude oil is 42. The sweet crude has an H_2S content of <10 ppm. The line is approximately 1.5 feet bgs at the release point.

Estimated area of impact 2164 sq ft.

Describe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Camille Reynolds	OIL CONSERVATION DIVISION	
Printed Name: Camille Reynolds	Approved by District Supervisor:	
Title: Remediation Coordinator	Approval Date:	Expiration Date:
E-mail Address: cjreynolds@paalp.com	Conditions of Approval:	Attached ☐
Date: 02/05/2007 Phone:505-441-0965		

* Attach Additional Sheets If Necessary

- Facility - fPAC0703829486
- incident - nPAC0703829581
- application - pPAC0703829660

RP# 1194

FEB 2007 Rece Hobbs OCD