

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	McGowan Working Partners Inc	Contact	Glenn Hepner
Address	P O Box 55809, Jackson MS 39296-5809	Telephone No.	601-982-3444
Facility Name	State	Facility Type	State

Surface Owner	State	Mineral Owner	State	Lease No.	B-2317
---------------	-------	---------------	-------	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	35	17S	34E	1190	South	2040	East	Lea

Latitude _____ Longitude _____

WTR 1'20'

NATURE OF RELEASE



Type of Release	Crude Oil/Produced Water	Volume of Release	15/200 bbls	Volume Recovered	185-190 bbls
Source of Release	Battery	Date and Hour of Occurrence	03/05/07 7:00 a.m. MST	Date and Hour of Discovery	03/05/07 9:30 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Chris Williams - District I Supervisor		
By Whom?	Jack Stevenson	Date and Hour	03/05/07 10:00 a.m. MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Saltwater pumps lost power and battery overflowed. Lost ground from power source. Electrician has been called in to evaluate entire electrical power system and repair as required.

Describe Area Affected and Cleanup Action Taken.*
Affected area is small area surrounding battery. Area has been flushed and vacuumed of all fluids; any soil contaminated has been removed to an OCD approved facility. Affected soil has been farmed and remediated with manure, disked and BLM mix grass seed planted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Glenn Hepner		Approved by District Supervisor: 	
Title: Regulatory Officer		Approval Date: 3.16.07	Expiration Date: _____
E-mail Address: glenn@mcgowanwp.com		Conditions of Approval:	
Date: 03/06/07 Phone: 601-982-3444		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

facility - PPAC0707926842
incident - PPAC0707926916
application - PPAC0707927022

RP# 1244