

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name SEMU #157	Facility Type Oil & gas well

Surface Owner Dr. J. McEasland	Mineral Owner BLM	Lease No. LC031670(A)
---	-------------------	-----------------------

STATE OF NM

LOCATION OF RELEASE


API# 3002 S 35538 0000

Unit Letter A	Section 30	Township 20S	Range 38E	Feet from the 660	North/South Line FNL	Feet from the 990	East/West Line FEL	County Lea
---------------	------------	--------------	-----------	-------------------	----------------------	-------------------	--------------------	------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 9 bbls	Volume Recovered 0
Source of Release 1" valve on floeline	Date and Hour of Occurrence 11/02/06	Date and Hour of Discovery 11/06/06 7:30
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		



Describe Cause of Problem and Remedial Action Taken.*

Valve handles left on valves. Valve was possibly opened by cattle due to cattle tracks around well. All valves were sealed closed.

Describe Area Affected and Cleanup Action Taken.*

Affected area consisted of 38,250 square feet of spray area, vegetation and well pad. No remediation planned at this time as per Landowner request. Landowner expressed concern about more damages occurring if remediated artificially. No fluid was recovered and no fluid was standing. Affected area had surface spray only. Contaminated caliche will be removed and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jesse A. Sosa</i>	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Approved by District Supervisor: <i>Jesse A. Sosa</i>	
Title: HSER Lead	Approval Date: 3.28.07	Expiration Date: _____
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/17/2006	Phone: (505)391-3126	

* Attach Additional Sheets If Necessary

incident - nPAC0708825731
application - nPAC0708825891

RP# 1223