

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>Latigo Petroleum, Inc.</i>	Contact <i>PATRICK ELLIS</i>
Address <i>P.O. Box 10340 Midland, Texas 79702</i>	Telephone No. <i>432 685-8148</i>
Facility Name <i>EVA E Blinberry Federal # 19</i>	Facility Type <i>injection line</i>

Surface Owner	Mineral Owner	Lease No. <i>NMLCO 64118</i>
---------------	---------------	------------------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>H</i>	<i>34</i>	<i>23S</i>	<i>37E</i>	<i>1420</i>	<i>North</i>	<i>20</i>	<i>East</i>	<i>LCA</i>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ API# *30025316760000*

#### NATURE OF RELEASE

Type of Release <i>Produced water</i>	Volume of Release <i>50 BBLs</i>	Volume Recovered <i>40 BBLs</i>
Source of Release <i>injection line</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>5-5-07 5-6-07</i> <i>faxed report 5-8-07</i>	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

*NA*

Describe Cause of Problem and Remedial Action Taken.\*

*Injection line was found to be leaking. Well was shut-in. All free fluid was picked up by vacuum truck.*

Describe Area Affected and Cleanup Action Taken.\*

*Leak gathered in small area near road. Highlander Environmental will inspect site, take soil samples and submit report for remediation plan.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Patrick L. Ellis</i>	OIL CONSERVATION DIVISION Approved by District Supervisor: <i>[Signature]</i>	
Printed Name: <i>PATRICK L. ELLIS</i>		
Title: <i>EH+S Supervisor</i>	Approval Date: <i>5-11-07</i>	Expiration Date: <i>7-11-07</i>
E-mail Address: <i>ellis.p@pogo-producing.com</i>	Conditions of Approval: <i>SUBMIT PLAN OF SAMPLE</i>	Attached <input type="checkbox"/>
Date: <i>5-8-07</i> Phone: <i>685-8148</i>		

\* Attach Additional Sheets If Necessary

*Incident - n PACO 713146662*  
*Operation - p PACO 713146788*

Documentation by 7-11-07

*RPT# 1315*