District I 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

							RATOR Initial Report Final Report			
Name of Company: Targa Midstream Services L P Contact: James Lingnau 505.394.2534, Chuck Tolsma 505.631.6026										
						Telephone No. (505) 394-2534				
Facility Name: Eunice Gathering System						Facility Type Gas Processing Plant				
Surface Owner: Edwin Johnson Mineral Owner:						Lease No.				
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/West Line	County	
	27	22S	37E			!			Lea	
145°										
Latitude 32.36843833 N Longitude 103.15923333 W  NATURE OF RELEASE										
Type of Release: Gas and Produced Liquids Volume of Release: Gas and Volume Recovered: None										
Type of Release. Gas and Floduced Eliquids						spray of liquid.				
Source of Release: 20" Gas Gathering Pipeline leak						Date and Hour of Occurrence: Date and Hour of Discovery				
							1PM April 23, 2007 2PM April 23, 2007			
Was Immediate Notice Given?						If YES, To Whom? Pat Caperton OCD				
Yes No Not Required						6				
By Whom? Rebecca Woodell						Date and Hour 1:40 PM April 24, 2007				
Was a Watercourse Reached?						If YES, Volume Impacting the Watercoarse.				
☐ Yes 🗷 No									Received &	
If a Watercourse was Impacted, Describe Fully.*										
A 20 inch gathering line 2 feet below the surface with 20 psig and 4.3mcfd of flow and less than 50 ppm of H2S developed at Paris released										
gas and liquids that were lying in the line. Field operators immediately blocked in line. Repairs were made to the line with a clamp and plans made to replace that section of line.										
Describe Area Affected and Cleanup Action Taken.*  Targa will replace pipe as needed. The area will be cleaned and tested per OCD guidelines.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of										
liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water,										
human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance										
with any other federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION										
Signature:						OLE CONSERVATION DIVISION				
Printed Name: Don Embrey						Approved by District Supervisor: Solves				
Title: Advisor Van Embry						Approval Dat	e: 5.11.07	Expiration I	Date: 7.11.07	
E-mail Address: dembrey@targaresources.com						Conditions of Approval:			Attached	
Date: 5/07/07 Phone: (432) 688-0546						SUBJUT DEUDERTION SAMPLIAS				
Attach Additional Sheets If Necessary										

incident - nPAC0713431028 application-pPAC0713431189