District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources,

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505



Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

## Release Notification and Corrective Action

						OPERAT	TOR		X Initia	l Report		Final Report	
Name of Co							lechel Painter						
Address P				79710	Telephone No. 432-684-4748 X 26								
Facility Nan	ne New]	Mexico "M"	State		Facility Type Water Storage								
Surface Owner Stat of New Mexico Mineral									Lease N				
Burrace O W	HOT DIME C	111011111111111111111111111111111111111											
			1 -			N OF REI		1	<del> </del>			<del></del>	
Unit Letter	Section 30	Township 22S	Range 37E	Feet from the 1710	Nort	h/South Line	Feet from the	East/V	Vest Line	County Lea			
	30	223	372	1710	14					Lua			
	<u> </u>		Ta	itude	Tanadanda					(wTR 250)			
			La	ude		Longitude					R 7	250	
				NA'	<b>TUR</b> I	E OF RELI	EASE			<u> </u>			
Type of Rele					Volume of Release 25 bbls Volume Recovered 25 bbls								
Source of Release Water Tank						Date and Hour of Occurrence 11:30 A.M. Date and Hour of Discovery 11:30 A.M. 3/14/07							
Was Immediate Notice Given?						If YES, To Whom?							
			] Yes [2	No 🗌 Not		- <b>,</b>						ļ	
Required												(	
By Whom?						Date and Hour							
Was a Watercourse Reached?  Yes X No						S, Volume Imp	acting the Water	course.					
			」 Yes <u>∠</u>	7 NO									
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	•									
									2.30	2324203		1	
										<b>**</b>			
Describe Cau	ise of Probl	em and Reme	edial Actio	n Taken.*				15		300	E. 1		
Hole in botto	m of tank							, 15 °		JdoH nnn	`;;		
									bevi	leney			
Describe Ass	- A 604- d	d C1	A -4: T-1							<del></del>			
Describe Are	a Amected	and Cleanup	Action 1 al	ten.≁				11.	,		`		
Cleaned with vacuum truck and backhoe									·. •	•		į	
						10 10 10 10 10 10 10 10 10 10 10 10 10 1							
I hereby certi	ify that the i	nformation or	iven above	is true and com	nlete to	the best of my	knowledge and u	m d auston		town are the second	000		
regulations a	ll operators	are required	to report a	nd/or file certain	release	notifications a	nd perform corre	ctive act	io mai purs ions for rel	eases which	may e	nuies and	
public health	or the envi	ronment. The	e acceptan	ce of a C-141 rep	ort by	the NMOCD n	narked as "Final F	Report" d	loes not rel	ieve the ope	rator o	of liability	
should their o	operations h	nave failed to	adequately	vinvestigate and	remedi	iate contaminat	ion that pose a th	reat to gr	ound wate	r, surface wa	iter, h	ıman health	
federal, state,	or local lav	ws and/or reg	ulations.	statice of a C-14	repon	does not renev	ve the operator of	respons	ibility for c	ompliance v	vith an	y other	
							OIL CONSE	RVA	TON DI	VISION			
Signature: Why lef auth						ON OUTBERT TRANSPORT						Ì	
Signature:	WW	<u>u</u> u	<u> </u>				ELUIRO ENG	R/	7				
Printed Name	e: Mechel I	Painter			Appro	oved by Distric	t-Supervisor:	~	LQ.				
							······································		P				
Title: Production Clerk					Approval Date: Expiration				Expiration	Date:			
E-mail Address: mechel@gp2energy.com					Conditions of Approval:								
		<u> Соврасно ву .</u>			Cond	mons of Appro	vai.			Attached		1	
Date: 3/15/0	)7	Phone: 43	2-684-474	8 X 26								1	
Attach Addi	tional Shee	ets If Necess	ary	71253	311	၁ I						1 122	
Attach Additional Sheets If Necessary  in Cident - n PACO7 1353.  application - p PACO7 135						2421				RP#133			
Vil	1	$\widetilde{\mathcal{L}}$	DAI	107125	32	536					K	(4)	
apa	Hical	uon-	OPT	-0/150							1	1.1	
· 07/		'							-				