

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 North A St., Bldg. 6, Midland, TX 79705-5406	Telephone No. 505.391.3126
Facility Name SEMU Drinkard #96	Facility Type Oil and Gas

Surface Owner BLM	Mineral Owner BLM	Lease No NM 0557686
--------------------------	--------------------------	----------------------------

LOCATION OF RELEASE

AP#30025251000000

Unit Letter I	Section 23	Township 20S	Range 37E	Feet from the 1650	North/South Line FSL	Feet from the 990	East/West Line FEL	County Lea
-------------------------	----------------------	------------------------	---------------------	------------------------------	--------------------------------	-----------------------------	------------------------------	----------------------

Latitude

Longitude

NATURE OF RELEASE

Type of Release Crude oil	Volume of Release 43bbl (33oil, 10water)	Volume Recovered (30oil, 5water)
Source of Release Stuffing box	Date and Hour of Occurrence 12/04/2006 7:00 am	Date and Hour of Discovery 12/04/2006 1:48 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD - Pat Caperton; BLM - Trisha Bad Bear	
By Whom? Jesse Sosa	Date and Hour 12/05/2006 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Stuffing box was leaking. Beam was shut down and stuffing box tightened to stop leak.		
Describe Area Affected and Cleanup Action Taken.* Affected area was 120'X150', vacuum truck was dispatched to recover standing fluid. Contaminated caliche was scraped and replaced with new caliche due to livestock in the vicinity.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Jesse A. Sosa		Approved by District Supervisor: 
Title: HSER Lead	Approval Date: 5-25-07	Expiration Date: 7-25-07
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval: Submit Final C-141 by 12/15/07	
Date: 12/05/2006	Phone: 505.391.3126	Attached <input type="checkbox"/>

• Attach Additional Sheets If Necessary

incident - NPAC0714546919
application - NPAC0714547018

W/Documentation

RP# 1374