


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Mickey D. Garner
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU 2738-006	Facility Type Oil and Gas

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No API#30-025-26516-00-0
--	--	---------------------------------------

LOCATION OF RELEASE

Unit Letter D	Section 27	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude **32.81305N** Longitude **-103.44989W**

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 51bbl (1oil, 50water)	Volume Recovered (0oil, 23water)
Source of Release EVGSAU 2738-006 casing valve	Date and Hour of Occurrence 1/6/07 0630hrs	Date and Hour of Discovery 1/6/07 1030hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson NMOCD	
By Whom? Brad Boroughs	Date and Hour 1/7/07 0800hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The discharge was caused by a packer leak or possible tubing failure, to be determined when well is pulled. A vacuum truck was called and 23 bbls of fluid were recovered. The downhole well problem will be repaired.

Describe Area Affected and Cleanup Action Taken.*

200'X75' of dry black soil/caliche rock road, pad and pasture with no cows present. The spill site will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Mickey D. Garner		Approved by District Supervisor:	
Title: HSE Lead		Approval Date: 5.27.07	Expiration Date: 7.27.07
E-mail Address: Mickey.D.Garner@conocophillips.com		Conditions of Approval: SUBMIT FINAL C-141 w/	
Date: 1/12/07 Phone: 505.391.3158		Attached <input type="checkbox"/>	

• Attach Additional Sheets If Necessary

ATTACHMENTS B9

incident - n PAC0715047999
application - pPA0715048129

RP#1387