

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	PHOENIX HYDROCARBONS OPER	Contact	ALAN STANDFER
Address	P O BOX 3638, MIDLAND, TX 79702	Telephone No.	432-557-8722
Facility Name	LJU #55	Facility Type	WIW

Surface Owner	CLARA JANE MILLER	Mineral Owner	FEDERAL	Lease No.	LOC55546
---------------	-------------------	---------------	---------	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
V 3	6	25S	37E	2310'	SOUTH	1650'	EAST	LEA COUNTY NM

Latitude 32°9'30.3N Longitude 103°11'55.2W

WTR < 55'

NATURE OF RELEASE

Type of Release	5 BBLS PROD WTR & 2 GALLONS SKIM OIL	Volume of Release	5 BBLS+2 G	Volume Recovered	0
Source of Release	injection line leak	Date and Hour of Occurrence	PM	Date and Hour of Discovery	2/4/07
Was Immediate Notice Given? within 24 hours	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Buddy Hill, also left message at Hobbs office		
By Whom?	Phyllis R. Gunter	Date and Hour	2/5-6/07 (Could not leave mess Hobbs on 2/5/07-no answer)		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.* INJECTION LINE LEAK, THE INJECTION LINE WAS REPAIRED

Describe Area Affected and Cleanup Action Taken.* THE AFFECTED AREA IS ROCKY TERRAIN WITH LITTLE VEGETATION AND THE BARDITCH BESIDE A ROAD, APPROXIMATELY 100' x 130'. THE SOIL WILL BE TURNED WITH A BACKHOE

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Phyllis R. Gunter</i>		OIL CONSERVATION DIVISION	
Printed Name: Phyllis R. Gunter		Approved by District Supervisor: <i>[Signature]</i>	
Title: Agent	Approval Date: 6.5.07	Expiration Date: 8.5.07	
E-mail Address: phygun@aol.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 2/8/07 Phone: 432-686-9869	SUBMITAL OF FINAL C-141 BY		

* Attach Additional Sheets If Necessary



RP# 1420