

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company – Chevron USA Inc	Contact – Nathan Mouser
Address – 2401 Ave O, Eunice NM 88231	Telephone No. – 505-394-1247
Facility Name – JR Phillips Battery	Facility Type – Tank Battery

Surface Owner – Raymond Byrd	Mineral Owner	Lease No.
------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter C	Section 6	Township 20S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 23° Longitude

NATURE OF RELEASE

Type of Release – Crude and water	Volume of Release 0.5 bbls oil, 10 bbls water	Volume Recovered – 0.5 bbls oil, 9 bbls water
Source of Release – 500 bbl tank	Date and Hour of Occurrence 10/9/06	Date and Hour of Discovery 10/9/06 07:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Water disposal line plugged, heater treater dumped water into tank. Tank overflowed. SI lease, unplug water disposal line.

Describe Area Affected and Cleanup Action Taken.\*

All fluids were contained inside bermed area and was picked up with vacuum truck and taken to disposal.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Nathan Mouser</u>	OIL CONSERVATION DIVISION	
Printed Name: Nathan Mouser	Approved by District Supervisor: <u>[Signature]</u>	
Title: Operations Supervisor	Approval Date: <u>6-5-07</u>	Expiration Date:
E-mail Address: NVMO@chevrontexaco.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/10/06	Phone: 505-394-1247	

\* Attach Additional Sheets If Necessary

RP# 1424