


District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>Latigo Petroleum, Inc</i>	Contact <i>Patrick Ellis</i>
Address <i>P.O. Box 10340 Midland, TX 79702</i>	Telephone No. <i>(432) 685-8148</i>
Facility Name <i>CENTRAL CORBIN QUEEN UNIT # 105</i>	Facility Type <i>inj well</i>

Surface Owner	Mineral Owner	Lease No. <i>NMLC 02 9489A</i>
---------------	---------------	--------------------------------

LOCATION OF RELEASE *API# 30025298980000*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>J</i>	<i>9</i>	<i>18S</i>	<i>33E</i>	<i>2310</i>	<i>FSL</i>	<i>2310</i>	<i>FEL</i>	<i>LEA</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Produced water</i>	Volume of Release <i>100 BBL</i>	Volume Recovered <i>0</i>
Source of Release <i>injection well</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>1:00pm 7-8-07 10:00AM 7-9-07</i> <i>LARRY JOHNSON NMOCD, TRISH BADBEAR BLM</i>	
By Whom? <i>PATRICK ELLIS</i>	Date and Hour <i>4:00pm 7-9-07</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

A 1/4" nipple and valve blew out on filter housing of injection well. Equipment was replaced.

Describe Area Affected and Cleanup Action Taken.*

The spill affected an area 80' x 100' on side of pad near wellhead. An area off the pad was affected measuring approx. 2' wide by 110' long. Highlander Environmental was contacted to sample area and evaluate for workplan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Patrick L. Ellis</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>PATRICK ELLIS</i>	Approved by District Supervisor: <i>[Signature]</i>	
Title: <i>EH+S Supervisor</i>	Approval Date: <i>7-11-07</i>	Expiration Date: <i>8-17-07</i>
E-mail Address: <i>ellis@pogo-producing.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>7-10-07</i> Phone: <i>(432) 770-0763</i>	<i>SUBMITAL OF WORKPLAN BY</i>	

* Attach Additional Sheets If Necessary

RP# 1401