

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company – Chevron USA Inc	Contact – Larry Williams
Address – 2401 Ave O, Eunice NM 88231	Telephone No. – 505-394-1247 (office), 505-390-7165 (cell)
Facility Name – CDU #426	Facility Type – Production well

Surface Owner Chevron	Mineral Owner	Lease No.
-----------------------	---------------	-----------

LOCATION OF RELEASE API # 3002526445

Unit Letter H	Section 29	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N 32° 26.903 Longitude W 103° 10.720

NATURE OF RELEASE API # 3002526445

WTR # 85'

Type of Release – Oil and Produced water	Volume of Release 2 oil 15 PW	Volume Recovered – 0
Source of Release – Split in 2" flowline	Date and Hour of Occurrence 7/10/2007 13:00	Date and Hour of Discovery 7/10/2007 13:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Billy Anderson	Date and Hour 7/10/2007 16:09	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Flowline had split causing release, dig up all the soil impacted during this release, haul to Sundance

Describe Area Affected and Cleanup Action Taken.*

10 X 20 area on fence line, sandy soil with sparse grass
Depth to ground water 86 to 96 feet.
chlorides 21,000
hydrocarbons 40.7

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Billy Anderson	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 7-18-07	Expiration Date:
E-mail Address billyanderson@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/16/2007	Phone: 505-441-5438	

* Attach Additional Sheets If Necessary

RP# 1494