District I 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

			Rele	ease Notific	catio	n and Co	rrective A	ction	n		•
						OPER!	ATOR		X Initia	al Report-	ノ <sub>ロ Final Repo</sub>
Name of Co	ompany	Plantation C	perating,	LLC	Contact J	ohn Allred					
Address	2203 Timb	erloch Place lands, TX 7		Telephone No. 281-296-7222							
Facility Name C.T. Bates #4 API #30-025-34404						Facility Type 120 BBL Test Tank					
Surface Ow	ner Joh	nny Chapma	Owner	Plantation Operating, LLC Lease No. 13411							
				LOCA	ATIO	N OF REI	LEASE				•
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County											
N	10	26S	37E	660'		South	2145'	,	West Lea		
	•		La	titude		Longitud	le				
						OF REL					rex80'
Type of Rele			Volume of Release 30 BBLS Volume Recovered 20 BBLS								
Source of Re	elease L		Date and Hour of Occurrence 7/6/07 – 12:00 p.m.  Date and Hour of Discovery 7/7/07 – 8:00 a.m.					scovery			
Was Immediate Notice Given?  X Yes ☐ No ☐ Not Required						If YES, To Whom? Gary Wink					
By Whom? John Allred						Date and Hour 7/9/07 – 11:20 a.m.					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
_								,		123	\$ C. E 0 3
N/A Describe Cau	use of Probl	em and Reme	dial Actio	n Taken.*  day night. Callecten.*  e. Digging out co					52728293	00 st.	2000 10 10 12 13 13 13 13 13 13 13 13 13 13 13 13 13
Lightning hit	fiberglass	water tank 7/6	6/07 on Fri	day night. Callec	l White	Buffalo Envir	onmental Service	es for pr	roper cléan	up.	
Describe Are	a Affected	and Cleanup	Action Tak	cen.*						3250	1000
Area affected	1 – 100 squa	are feet off pa	d in pastur	e. Digging out co	ontamin	ated dirt and h	nauling to landfill	i.			
regulations a public health should their or the enviro	ify that the ll operators or the envious operations had not be the control of the	information g are required t ronment. The nave failed to	iven above o report ar e acceptance adequately OCD accep	e is true and comp nd/or file certain repose of a C-141 repose	olete to to elease re ort by the emedian	the best of my notifications are NMOCD mate contaminations.	knowledge and und perform correctance as "Final Foon that pose a three the operator of	understa ctive act Report" ( reat to g	and that purs tions for rel- does not rel- ground water sibility for c	suant to NM eases which ieve the ope r, surface w compliance	n may endanger erator of liability ater, human health with any other
Signature:						OIL CONSERVATION DIVISION					
Printed Name	e: John A		Approved by District Supervisor:								
Title: Engi	ineer <b>V</b>			Approval Date: 7-18.07 Expiration Date: 9.18.87							
E-mail Addre	ess: jallre	d@plantation	petro.com	77.6		Conditions of	_		£	Attached	
Date:	7/9/07			Phone: 281-296-7	222	JUBM T	FINAL C.	-141	/دن		
* Attach Addi	tional She	ets If Necess	ary			SUPPORT	THE BOC	U 11/21	4 317ATE	s Be	- L 10