

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 <sup>TH</sup> STREET	Telephone No. 505.748.1471	
Facility Name ROSEMARY BOOSTER	API Number	Facility Type PIPELINE

Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No
--------------------------	--------------------------	----------

LOCATION OF RELEASE

Unit Letter L	Section 6	Township 22S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 50 B/PW	Volume Recovered 50 B/PW
Source of Release PIPELINE	Date and Hour of Occurrence 7/28/07 11:00 AM	Date and Hour of Discovery 7/28/07 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? GARY WINK	
By Whom? SHERRY BONHAM	Date and Hour 7/28/07 12:51 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

ELECTRICAL PROBLEM CAUSED BY THUNDERSTORM IN THE AREA PRODUCED A PUMP PROBLEM WHICH RESULTED IN A WATER LINE LEAK. TURNED PUMP OFF AND SHUT VALVE ON WATER LINE. REPAIRS MADE.

Describe Area Affected and Cleanup Action Taken.\*

APPROXIMATELY 30' X 4' AREA AFFECTED. HEAVY RAIN IN AREA. IMMEDIATELY CALLED IN VACUUM TRUCK VACUUMED STANDING FLUIDS

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Sherry Bonham	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: 9.11.07	ENVIRONMENTAL ENGINEER Expiration Date: 10.12.07
E-mail Address: sherryb@ypcnm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 10, 2007	Phone: 505.748.1471	

\* Attach Additional Sheets If Necessary

②

RP #1524