


NM1 - 3

MONITORING REPORTS

YEAR(S):

1988-1989

MAP



- LEGEND**
- △ PIT FLOOR
 - x PIT MARGIN
 - TEST HOLE
 - △ INSTRUMENT STATION
 - Test Hole did not encounter Triassic
 - Test Hole encountered Triassic
 - ▲ Triassic exposed
 - △ Triassic close to surface, but not exposed
 - ▬ DIKE
 - ▬ CORE TRENCH
 - ⊙ CORE HOLES

0 100 200 300 400 500 ft



Figure 2

LEA COUNTY NEW MEXICO
 WALLACH BROTHERS
 TRIASSIC MAP