

GW-4

RECEIVED

OCT 13 2003

Oil Conservation Division
Environmental Bureau

Groundwater Investigation Summary Report

ChevronTexaco Eunice #2 (North) Plant
Eunice, Lea County, New Mexico

REPORTS

Volume 2
Figures

10/13/2003

October 9, 2003


PREPARED FOR


ChevronTexaco Exploration & Production
Company

ARCADIS
Infrastructure, buildings, environment, communications



- Explanation**
- Monitor Well Location
 - ▲ Recovery Well Location
 - ★ Water Supply Well Location
 - 0.011 Benzene Concentration (mg/L)
 - NS Not Sampled
 - Benzene Contours
 - Line Of Equal Concentration (mg/L)
 - Contour Interval — Logarithmic
 - Practical Boundary Separating Fully-Penetrating Versus Partially-Penetrating Well Completions



 1004 N. Big Spring Street, Suite 300 Midland, TX 79701-3383 Tel 432 687 5400 Fax 432 687 5401					Drawn By H. Clardy		Drawing Date 26 September 2003		File Location [AutoCAD] \DWG \ChevronTexaco \North Eunice \MT000700.004		File Name MT700491.dwg		Unique Number 31-014-00563		Project Director M. Hagan		Area Manager A. Schmidt	
					ChevronTexaco Exploration & Production Company North Eunice Plant Groundwater Investigation					Task Manager L. Markham		Technical Review S. Tischer						
					Deep Groundwater Isoconcentration Map (September, 2002)					Project Number MT000700.0004		Figure 36						
					Benzene (mg/L)													
					Eunice #2 (North) Gas Plant, Lea County, New Mexico													