



GW-4

RECEIVED

OCT 13 2003

Oil Conservation Division
Environmental Bureau

Groundwater Investigation
Summary Report

ChevronTexaco Eunice #2 (North) Plant
Eunice, Lea County, New Mexico

REPORTS

Volume 2
Figures

10/13/2003


October 9, 2003

ARCADIS
Infrastructure, buildings, environment, communications

PREPARED FOR

ChevronTexaco Exploration & Production
Company

- Explanation**
- Monitor Well Location
 - ▲ Recovery Well Location
 - ★ Water Supply Well Location
 - 4.5 BTEX Concentrations (mg/L)
 - NS Not Sampled
 - BTEX Contour
 - 1.0 Line of Equal Concentration (mg/L)
Contour Interval — Logarithmic
 - Practical Boundary Separating Fully-
Penetrating Versus Partially-Penetrating
Well Completions



Scale in Feet
0 200 400 800

Copyright © 2003



1004 N. Big Spring Street, Suite 300
Midland, TX 79701-3383
Tel 432 687 5400 Fax 432 687 5401

Drawn By
H. Clardy

Drawing Date
19 March 2003

File Location
AutoCAD/DWG/ChevronTexaco\North Eunice\MT000700.004

File Name
MT700419.dwg

Unique Number
31-014-00450

Project Director
M. Hagan

Area Manager
A. Schmidt

Task Manager
L. Markham

Technical Review
S. Tischer

Project Number
MT000700.0004

Figure
45

ChevronTexaco Exploration & Production Company
North Eunice Plant Quarterly Monitoring
Shallow Groundwater Isoconcentration Map (December, 2002)
BTEX (mg/L)
Eunice #2 (North) Gas Plant, Lea County, New Mexico

No.	Date	Revision Description	By	Ckd