

GW-4

RECEIVED

OCT 13 2003

Groundwater Investigation Summary Report

Oil Conservation Division
Environmental Bureau

ChevronTexaco Eunice #2 (North) Plant
Eunice, Lea County, New Mexico

REPORTS

Volume 2
Figures

10/13/2003

October 9, 2003



Infrastructure, buildings, environment, communications


PREPARED FOR

ChevronTexaco Exploration & Production
Company



Explanation

- Monitor Well Location
- ▲ Recovery Well Location
- ★ Water Supply Well Location
- 3.7 Benzene Concentrations (mg/L)
- NS Not Sampled
- Benzene Contour
- .5 Line of Equal Concentration (mg/L)
- Contour Interval — Logarithmic
- - - Practical Boundary Separating Fully-Penetrating Versus Partially-Penetrating Well Completions



No.	Date	Revision Description	By	Ckd

1004 N. Big Spring Street, Suite 300
Midland, TX 79701-3383
Tel 432 687 5400 Fax 432 687 5401

Drawn By H. Clardy	Drawing Date 06 June 2003	File Location AutoCAD DWG\ChevronTexaco\North Eunice\MT000700.004	File Name MT700427.dwg	Unique Number 31-014-00449	Project Director M. Hagan	Area Manager A. Schmidt
ChevronTexaco Exploration & Production Company North Eunice Plant Groundwater Investigation Shallow Groundwater Isoconcentration Map (December, 2002) Benzene (mg/L) Eunice #2 (North) Gas Plant, Lea County, New Mexico				Task Manager L. Markham	Technical Review S. Tischer	Project Number MT000700.0004
					Figure 47	

copyright © 2003