

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company - Chevron USA Inc	Contact - Billy Anderson
Address - 2401 Ave O, Eunice NM 88231	Telephone No. - 505-394-1237
Facility Name - CDU 111	Facility Type - Injection well

Surface Owner--- Chevron	Mineral Owner--	Lease No. <u>APL</u>
--------------------------	-----------------	----------------------

LOCATION OF RELEASE

AP1 # 30025068450000

Unit Letter G	Section 28	Township 21 S	Range 37 E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release 20 BBLS	Volume Recovered - 0
Source of Release - Injection Line	Date and Hour of Occurrence 1/18/2007 10am	Date and Hour of Discovery 1/18/2007 10am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	


If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Ditching machine hit injection line Shut in well

Describe Area Affected and Cleanup Action Taken.\*

Sandy ground, water stayed in right of way just around leak-----Depth to ground water app 50 ft



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Billy Anderson</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Billy Anderson</u>		Approved by District Supervisor:	
Title: <u>HES Champion</u>	Approval Date: <u>1/16/08</u>	Expiration Date: <u>4/16/08</u>	
E-mail Address: <u>BillyAnderson@Chevron.com</u>	Conditions of Approval: <u>Need final report! Cll</u>	Attached <input type="checkbox"/>	
Date: <u>1-19-07</u>	Phone: <u>394-1237</u>		

\* Attach Additional Sheets If Necessary

RP# 1726