State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Fran	cis Dr., Santa	a Fe, NM 87505	5	Sa	nta Fe	e, NM 875	505				side of form
			Rele	ease Notific	ation	and Co	orrective A	ction			
						OPERA	ГOR		🛛 Initia	al Report	Final Report
Name of Company Centurion Pipeline, LP						Contact Becky Moore					1
Address 2200 East CR 90, Midland, TX 79706						Telephone No. 432-978-8067					
Facility Name 8" Gathering Line into Gladiola						Facility Type Sweet Crude Oil Pipeline					
Surface Ow	ner Wesle	ey Harris	Mineral O	wner	Lease No.						
				LOCA	IOIT .	N OF RE	LEASE				
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	Vest Line	County	
	9	13 S	38 E							Lea	
	1.7	15.5		L	10 721	T an aide	l			1/04	
				Latitude <u>N 33'</u>				<u>IU</u>			
- 47.1				NAT	URE	OF REL					
Type of Rele Source of Re			tate line, on the 8'	19				Hour of Discovery			
		e into Gladiol	tate nne, on the o		01/18/08 01/18/08 01/18/08 at 2:						
Was Immedia		Given?] No 🔲 Not Re	quired	If YES, To Whom?						
By Whom?			· · · · · · · · · · · · · · · · · · ·		Date and Hour 01/19/08 at 10 am						
Was a Water	course Read		No		If YES, Volume Impacting the Watercourse RECEIVED						
If a Watercou	urse was Im	pacted, Descr	ibe Fully. ⁴	k -					(1939-10 Velice - 19	CONTRACTOR CONTRACTOR	
									IANE 2	2 5 2008	
contained ur contaminate bottom of th Describe Are Area affecte deep were at request of th The pipeline	ntil an emer d soil was e excavation a Affected d at the sou ffected. Es he landown b is being re	rgency one ca being complet on and from t and Cleanup A arce of the lea timated 1200 er clean soil v eplaced with 3	all was cle ted on 8/2 he stock p Action Tak ak is apx. Cu. Yds. will be use 300' of ne	ared with the Sta 3/08. Affected so piles were taken 8 cen.* 40' x 50' and apx of contaminated ed from the Lando	te of N il was l /23/08 . 10' in soil is c owner's he sour	M on 8/22/08 brought to th for lab analy depth. Also currently bei s orchard wh ce of the cor	due to state of e surface and st sis to ensure NM an area of apx. ng hauled offsite hich is within pro- rosion. A final (fice close aged on 1 State c 250' in 1 e to Gane oximity C-141 wi	ure during plastic at clean up lev length alor dy Landfil of the affed	ng the pipeline RO I West of Tatum.	tion of the from the W and 12" At the
regulations a public health should their o or the environ	ll operators or the enviro operations h nment. In a	are required to ronment. The have failed to a	o report an acceptance adequately OCD accept	nd/or file certain re ce of a C-141 report investigate and re	clease no rt by the mediate	otifications as NMOCD m e contaminati	nd perform correc arked as "Final R on that pose a thr e the operator of	ctive acti leport" do reat to gr responsi	ons for rele oes not reli ound water bility for co	uant to NMOCD ru eases which may en eve the operator of , surface water, hur ompliance with any DIVISION	danger liability nan health
Signature: PANOON						Approved by District Supervisor:					
Printed Name	e: Becky M	loore		<u></u>			District Supervis	C	hus	William	•
Title: Comp	liance Coor	dinator				Approval Dat	te: 1/28/	68 F	Expiration I	Date: 4/28/0	8
E-mail Addre	ess: Rebecc	a_Moore@ox	y.com		(Conditions of	f Approval:			Attached	
Date: 01/23/0				Phone: 432-978-8	067						
Attach Addi	tional Shee	ets If Necess	ary							RP=	F1762