

GW - 004

2006 MONITORING REPORTS

03/12/2007



Note: It is believed previous molasses injection resulted in laboratory interferences and elevated detection limits in affected wells.

No warranty is made by SECOR International, Inc. as to the accuracy, reliability, or completeness of these data. Original data were compiled from various sources. This information may not meet National Map Accuracy Standards. This product was developed electronically, and may be updated without notification. Any reproduction may result in a loss of scale and/or information.

 2321 Club Meridian Drive, Suite E Okemos, Michigan PHONE: (517) 349-9499 FAX: (517) 349-6863	FOR:  EUNICE NORTH GAS PLANT EUNICE, NEW MEXICO		TOTAL CHROMIUM ISOCONCENTRATION MAP - SHALLOW WELLS (JANUARY/FEBRUARY 2006)		FIGURE: 7
	JOB NUMBER: 89CH-49410.07	DRAWN BY: RDT	CHECKED BY:	APPROVED BY:	
			DATE: 05/18/06		