


GW - 004

# 2006 MONITORING REPORTS

03/12/2007



- Explanation**
- MW046 + Monitoring Well Location
  - <0.015\* Dissolved Chromium Concentration (mg/L)
  - \* Value not used to generate contours
  - RW002 + Recovery Well Location
  - IW006 + Injection Well Location
  - ROWLANDWW + Water Supply Well Location
  - 0.05 - Chromium Isoconcentration Contour
  - - - - - Inferred Isoconcentration Contour

Note: It is believed previous molasses injection resulted in laboratory interferences and elevated detection limits in affected wells.

No warranty is made by SECOR International, Inc. as to the accuracy, reliability, or completeness of these data. Original data were compiled from various sources. This information may not meet National Map Accuracy Standards. This product was developed electronically and may be updated without notification. Any reproduction may result in a loss of scale and/or information.

<p>2321 Club Meridian Drive, Suite E Okemos, Michigan PHONE: (517) 349-9499 FAX: (517) 349-8863</p>	<p>FOR:  CHEVRON</p> <p>EUNICE NORTH GAS PLANT</p> <p>EUNICE, NEW MEXICO</p>	<p>DISSOLVED CHROMIUM ISOCONCENTRATION MAP - DEEP WELLS (JUNE/JULY 2006)</p>	<p>FIGURE: <b>12</b></p>
	<p>JOB NUMBER: 89CH49410.07</p> <p>DRAWN BY: RDT</p> <p>CHECKED BY:</p> <p>APPROVED BY:</p> <p>DATE: 10/13/2006</p>		