


GW - 004

2006 MONITORING REPORTS

03/12/2007



- Explanation**
- MW046 ● Monitoring Well Location
 - TPH Concentration (mg/L)
 - * Value not used to generate contours
 - RW002 ● Recovery Well Location
 - IW006 ● Injection Well Location
 - ROWLANDWW ● Water Supply Well Location
- TPH Concentration is sum of Diesel and Gasoline
- 4 — TPH Isoconcentration Contour
 - 10 --- Inferred Isoconcentration Contour
 - < Only one of the constituents (diesel or gasoline) was detected

Note: It is believed previous molasses injection resulted in laboratory interferences and elevated detection limits in affected wells.

 2321 Club Meridian Drive, Suite E Okemos, Michigan PHONE: (517) 349-9499 FAX: (517) 349-6883	FOR: EUNICE NORTH GAS PLANT EUNICE, NEW MEXICO	TPH ISOCONCENTRATION MAP (JUNE/JULY 2006)		FIGURE: 24
	JOB NUMBER: 89CH49410.07	DRAWN BY: RDT	CHECKED BY:	APPROVED BY:
				DATE: 10/13/2006