

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849, Eunice NM 88231	Telephone No. 505-390-4186
Facility Name EBDU #61	Facility Type
Surface Owner	Mineral Owner
Lease No. 30-025-38280	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	14	21S	37E	2370	South Line	990	East Line	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil/Wtr	Volume of Release 6	Volume Recovered 5
Source of Release Pressure gauge blew out	02/01/08	02/01/08
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Pressure gauge blew out. Vac truck was called out to suck up fluid.

RECEIVED

FEB 14 2008

Describe Area Affected and Cleanup Action Taken.*
Apache will clean contaminated area and follow NMOCD guidelines for remediation.

HOBBS OCD

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	<i>[Signature]</i> Approved by District ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Tech	Approval Date: 2.14.08	Expiration Date: 4.14.08
E-mail Address: Natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/14/08 Phone: 505-390-4186		IRP 1788

* Attach Additional Sheets If Necessary