District I 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUN 20 2008

Form C-141 Revised October 10, 2003

are to be presented to OCD

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

OCD-ARTESIA Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

i Sebosia	5 E / 7 O /	•	Rel	ease Notific	atio	n and Co	orrective A	ction	l				
NSE808192	L56221	•				OPERA'	ГOR			al Report		Final Report	
Name of Company Fairway Resources Operating LLC 241548													
Address 53	8 Silicon I	Orive, Suite	thlake, TX 7609	2	Telephone No. 817-416-1946								
Facility Nar	ne South	Red Lake II	Unit #43	30-015-2391	13	Facility Typ	e oil well						
Surface Ow	ner State	of New Mex	Mineral O	wner	State of New Mexico Lease No. NM109695X								
				LOCA	TIO	N OF REI	LEASE						
Unit Letter	Unit Letter Section Township Range Feet from the North					/South Line	South Line Feet from the East/West Line			County			
"K" 36 17-S 27-E 1,650 South							1,650	West		Eddy			
	Latitude 32.7877800 Longitude -104.2350200												
	NATURE OF RELEASE												
Type of Release Produced water and crude oil Source of Release Flowline leak near the wellhead							Volume of Release 25 bbls est. Volume Recovered 20 bbls est.						
Source of Re	lease Flow	ead	Date and Hour of Occurrence Date and Hour of Discovery 6/16/08 unknown time 6/17/08 8:00am										
Was Immedia	te Notice C	No □ Not Rec	If YES, To Whom?										
By Whom?	Kenneth Pe			Date and Hour 6/17/08									
Was a Water			If YES, Volume Impacting the Watercourse.										
] No											
If a Watercou	rse was Imp	pacted, Descri	be Fully.'	k									
Describe Cause of Problem and Remedial Action Taken.*													
A leak developed in a steel nipple at the wellhead flowline connection. The nipple was replaced, repairing the leak.													
Describe Area	Affected a	nd Cleanup A	ction Tak	cen.*									
The affected a	rea was the	well location	, lease roa	ad, and area immed	liately	along the leas	e road.						
submitted for	approval w	ithin 30 days	of this no										
regulations all public health should their o	operators a or the envir perations ha ment. In a	are required to onment. The ave failed to a ddition, NMO	report an acceptance dequately CD accep	e is true and comple ad/or file certain relate of a C-141 report investigate and restance of a C-141 re	lease not t by the mediate	otifications ar e NMOCD ma e contamination	nd perform correct arked as "Final Re on that pose a thre	tive acti eport" de at to gr	ons for rele oes not reli ound water	eases which n ieve the opera r, surface wate	nay end ator of er, hun	danger liability nan health	
						OIL CONSERVATION DIVISION							
Signature: Keell Davie						Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the						ith confirmation	
Printed Name	: Kenneth l	Pearce				Approved by	District Superviso	or: b 4		Expiration Date.			
Title: Operations Engineer						Approval Dat	e: 1-10-08	E	Expiration	Date: 9-12	-08	1	
E-mail Address: kpearce@fairwayresources.com						Conditions of Approval:				Attached	П		
Date: June 17, 2008 Phone: 817-416-1946						The plan must include general site characteristics, site ranking score, soil remediation action levels, soil remediation methods.					2 RP - 188		
Attach Addit	ional Shee				a	nd planned analy other COCs as app	tical testing for TPH, E dicable. Please use the aks, Spills, & Releases	3-TEX, Cl e "Guideli	nlorides or any nes for	Notify OCD	48 hou		

Remediation of Leaks, Spills, & Releases" as your guide. This

http://www.emnrd state nm us/ocd/documents/7C_spill1.pdf

document may be found at the following link.