

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Oxy USA WTP Ltd.	Contact: Chancey Summers (CJ)
Address: 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No: 505.397.8216 or 505.631-9436
Facility Name: Meyers Langlie Mattix Unit CTB #145	Facility Type Production: Oil

Surface Owner: James Doom	Mineral Owner: BLM	Lease No.
----------------------------------	---------------------------	-----------

LOCATION OF RELEASE

API 30.025.11012

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
'H'	5	24-S	37-E					Lea

Latitude N 32°14' 50.60" Longitude W 103°11' 04.90"

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 5 BO X 500 BW	Volume Recovered: 400
Source of Release: Over flow Tanks	Date and Hour of Occurrence: 06/06/2008 07:00 AM	Date and Hour of Discovery: 06/06/2008 07:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Chris Williams (NMOCD)	
By Whom? C.J. Summers	Date and Hour: 06/06/2008 09:39 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	



RECEIVED
JUN 19 2008
HOBBS OGD

If a Watercourse was Impacted, Describe Fully *N/A

Describe Cause of Problem and Remedial Action Taken.* **Electrical power failure caused over flow tanks to run over to communication error. Power will be restored and injection will be returned to normal battery operations.**

Describe Area Affected and Cleanup Action Taken.*
Produced fluid ran across location pad and ran east into sandy pasture. Picked up all fluid possible via vacuum truck. Recovered ????????. Area will be remediated to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by District Supervisor:  ENVIRONMENTAL ENGINEER	
Title: HES Specialist	Approval Date: 7.8.08	Expiration Date: 9.8.08
E-mail Address: chancey_summers@oxy.com	Conditions of Approval: SUBMIT FINAL C.141	Attached <input type="checkbox"/> IRP# 1898
Date: 06/06/2008 Phone: 575-397-8216	w/ TEST RESULTS & DOCUMENTATION BY 9.8.08	

* Attach Additional Sheets If Necessary

FGRL 0821955883
NGRL 0821956879

NOTE: NEED SIGNATURE ON ALL SUBMITTALS & IRP # ON FINALS SUBMITTALS

