

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUL 18 2008  
OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

i 5600822457133  
15600822456978

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Judah Oil, LLC	Contact	James B. Campanella
Address	P.O. Box 568, Artesia, NM 88210	Telephone No.	575-746-1280
Facility Name	Oxy T-Bone Fed #1	Facility Type	Salt Water Disposal

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	SWD-950
---------------	-----	---------------	-----	-----------	---------

30-015-32122

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	33	185	31 E	660	North	1980	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	23 bbls of oil	Volume Recovered	21 bbls of oil
Source of Release	Oil Tank	Date and Hour of Occurrence	July 11, 2008 at 8:30pm	Date and Hour of Discovery	July 11, 2008 at 11:30pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos with BLM and Mike Bratcher with NMOCD		
By Whom?	James B Campanella	Date and Hour	July 12, 2008 at 8:00am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*



Water truck unloaded PW into oil tank. Removed contaminated gravel and replaced with new gravel. Treated contaminated area with micro-blaze.

Put back on oil line to oil tank

Describe Area Affected and Cleanup Action Taken.\*

Spill contained in lined, fixed all of the area. The vacuum truck pulled 21 bbls of oil and put back into gun barrel.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: James B. Campanella	Approved by District Supervisor: 	
Title: Manager/President	Approval Date: 8-11-08	Expiration Date: N/A
E-mail Address: juhadoil@yahoo.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: July 18, 2008	Phone: 575-746-1280	

\* Attach Additional Sheets If Necessary

2RP-214