

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company	Dakota Resources Inc.(I)	Contact	Rick Maddox
Address	4914 N. Midkiff Midland, Texas 79705	Telephone No.	(432) 697-3420
Facility Name	Wallen Federal #2	Facility Type	Oil
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	30 025 23985

LOCATION OF RELEASE

Unit Letter	Section 20	Township 20S	Range 34E	Feet from the 330'	North/South Line FNL	Feet from the 330'	East/West Line FWL	County LEE
-------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil & Water	Volume of Release	90 bbls	Volume Recovered	88bbls
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	
Check valve on SWD failed and Well back flowed		Early AM, 7-14-08		8:00 AM, 7-14-08	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Trisha Bad Bear, BLM - Buddy Hill, OCD		
By Whom?	Rick Maddox	Date and Hour	9:30 AM 7-14-08		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Check valve on the SWD failed and well back flowed into tanks.

Called out backhoe and Vacuum truck, pulled fluid from firewall and 2 bbls of ground outside firewall. Dug up contaminated soil and replaced w/ fresh soil. Working on plan for inside firewall.

Describe Area Affected and Cleanup Action Taken.*

Inside firewall and 10 x10 area on north side of firewall

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>R. Maddox</i>	OIL CONSERVATION DIVISION	
Printed Name: Rick Maddox	Approved by District Supervisor: <i>G. Johnson</i>	
Title: Operations Manager	ENVIRONMENTAL ENGINEER	
E-mail Address:	Approval Date: 7-18-08	Expiration Date: 9-18-08
Date: 7-15-08	Conditions of Approval:	Attached <input type="checkbox"/> 1RP# 1905
Phone: 432/697-3420		

* Attach Additional Sheets If Necessary

FGRL 0821335823