

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Devon Energy Production Co-. L.P.	Contact Vivian Rodriguez
Address P.O. Box 250, Artesia, NM 88211-0250	Telephone No. 575-748-0173
Facility Name Morton Solid State #1	Facility Type Oil Well P & A'd

Surface Owner Nancy Etcheverry	Mineral Owner	Lease No. 30-025-26350
--------------------------------	---------------	------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	4	15S	34E	2160'	North	990	West	Lea County

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

*4260'*

**NATURE OF RELEASE**

Type of Release Don't Know	Volume of Release DK	Volume Recovered DK
Source of Release DK	Date and Hour of Occurrence DK	Date and Hour of Discovery DK
Was Immediate Notice Given? Don't know <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacted the Watercourse	

**RECEIVED**  
**JIA E. MAIL**  
**AUG 25 2008**  
**HOBBS OCD**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

While cleaning P & A'd location to land owners specifications we found an area that need to be delineated due to hydrocarbon staining. As per Larry Johnson the ground water is at 70'.

Describe Area Affected and Cleanup Action Taken.\*

An area approximately 30' X 60' has hydrocarbon staining. The clean up has been given to Whole Earth for investigation protocol.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u> <i>L. Johnson</i>	
Printed Name: Vivian Rodriguez	Approved by District Superintendent <b>ENVIRONMENTAL ENGINEER</b>	
Title: Tech II	Approval Date: <b>8-25-08</b>	Expiration Date: <b>9-25-08</b>
E-mail Address: Vivian.rodriguez@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/11/08 Phone: 575-748-0173		<b>IRP#1931</b>

\* Attach Additional Sheets If Necessary

FGRL0824026688