

RECEIVED

575-748-4662

District I
1625 N. French Dr., Hobbs, NM 87400State of New Mexico
Energy Minerals and Natural ResourcesForm C-141
Revised October 10, 2003District II
1301 W. Grand Avenue, Artesia, NM 87210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Hobbs, NM 87401Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form**Release Notification and Corrective Action****FINAL****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street		Telephone No. 505-748-1471
Facility Name Mescalero ARL, State #1	API Number 30-025-336969	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. VA-0621
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 2	Township 10S	Range 32E	Feet from the 330	North/South Line South	Feet from the 330	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 33.46878 Longitude 103.63456

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 25 B/O	Volume Recovered 10 B/O
Source of Release Production Tank	Date and Hour of Occurrence 1/13/2008 AM	Date and Hour of Discovery 1/13/2008 AM
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Mark Whitaker/NMOCD, District I	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 1/14/2008, 8:38 AM (VM) & 8:42 AM (E-mail)	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.
N/ADescribe Cause of Problem and Remedial Action Taken.⁺

Oil hauler did not pick up load of oil and tank ran over, vacuum truck and excavation crew called to location.

Describe Area Affected and Cleanup Action Taken.⁺

An approximate area of 36' X 12'. All inside berm. Vacuum truck picked up remaining oil; contaminated soils were excavated and taken to an OCD approved facility. Vertical and horizontal delineation was made and corrective action taken. Depth to Ground Water: 50-99' (approx. 65'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on enclosed information, Yates Petroleum Corporation requests closure, stockpiled soils were blended but are above RRAL's, and these soils will be taken to an OCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	ENVIRONMENTAL ENGINEER	
E-mail Address: boba@ypcorp.com	Approval Date: 10.8.08	Expiration Date: _____
Date: Friday, April 25, 2008	Phone: 505-748-4217	Conditions of Approval: _____

Attached ☐

IRP# 1751

⁺ Attach Additional Sheets If Necessary

FGRLO829453659

Analytical Report 307611

for

Yates Petroleum Corporation

Project Manager: Robert Asher

Mescalero ARL State # 1

30-025-33696

14-JUL-08



12600 West I-20 East Odessa, Texas 79765

**Texas certification numbers:
Houston, TX T104704215**

**Florida certification numbers:
Houston, TX E871002 - Miami, FL E86678 - Tampa, FL E86675
Norcross(Atlanta), GA E87429**

**South Carolina certification numbers:
Norcross(Atlanta), GA 98015**

**North Carolina certification numbers:
Norcross(Atlanta), GA 483**


**Houston - Dallas - San Antonio - Austin - Tampa - Miami - Latin America
Midland - Corpus Christi - Atlanta**

**Sample Cross Reference 307611****Yates Petroleum Corporation, Artesia, NM**

Mescalero ARL State # 1



Sample Id	Matrix	Date Collected	Sample Depth	Lab Sample Id
GS/Comp-001	S	Jul-09-08 10:07	1 - 1 ft	307611-001
GS/Comp-002	S	Jul-09-08 10:22	2 - 2 ft	307611-002
GS/Comp-003	S	Jul-09-08 10:38	3 - 3 ft	307611-003



Certificate of Analysis Summary 307611

Yates Petroleum Corporation, Artesia, NM

Project Name: Mescalero ARL State # 1

Project Id: 30-025-33696

Contact: Robert Asher

Project Location: Lea County

Date Received in Lab: Thu Jul-10-08 01:40 pm

Report Date: 14-JUL-08

Project Manager: Brent Barron, II

<i>Analysis Requested</i>	<i>Lab Id:</i>	307611-001	307611-002	307611-003			
	<i>Field Id:</i>	GS/Comp-001	GS/Comp-002	GS/Comp-003			
	<i>Depth:</i>	1-1 ft	2-2 ft	3-3 ft			
	<i>Matrix:</i>	SOIL	SOIL	SOIL			
	<i>Sampled:</i>	Jul-09-08 10:07	Jul-09-08 10:22	Jul-09-08 10:38			
Inorganic Anions by EPA 300	<i>Extracted:</i>	Jul-10-08 15:01	Jul-10-08 15:01	Jul-10-08 15:01			
	<i>Analyzed:</i>						
	<i>Units/RL</i>	mg/kg RL	mg/kg RL	mg/kg RL			
Chloride		ND 5.00	ND 5.00	ND 5.00			

This analytical report, and the entire data package it represents, has been made for your exclusive and confidential use. The interpretations and results expressed throughout this analytical report represent the best judgment of XENCO Laboratories. XENCO Laboratories assumes no responsibility and makes no warranty to the end user of the data herein presented. Our liability is limited to the amount provided for this work order unless otherwise agreed to in writing.

Since 1990 Houston - Dallas - San Antonio - Austin - Tampa - Miami - Latin America - Atlanta - Corpus Christi


Brent Barron
Odessa Laboratory Director

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Phone: 412-563-1800
Fax: 412-563-1719

Project Name Escadero ARL State #1

Project # 30-025-33596

Project Loc Lia County

FD 6 105532

Report Form: ☒ Standard ☐ IRP ☐ NRCES

e-mail: boba@ypca.net.com

[illegible]

Environmental Lab of Texas
Variance/ Corrective Action Report- Sample Log-In

Client:

Yates Pet.

Date/ Time:

7 10 08 13:40

Lab ID #:

307611

Initials:

al**Sample Receipt Checklist**

			Client Initials
#1 Temperature of container/ cooler?	Yes	No	2.5 - C
#2 Shipping container in good condition?	Yes	No	
#3 Custody Seals intact on shipping container/ cooler?	Yes	No	Not Present
#4 Custody Seals intact on sample bottles/ container?	Yes	No	Not Present
#5 Chain of Custody present?	Yes	No	
#6 Sample instructions complete of Chain of Custody?	Yes	No	
#7 Chain of Custody signed when relinquished/ received?	Yes	No	
#8 Chain of Custody agrees with sample label(s)?	Yes	No	ID written on Cont. Lid
#9 Container label(s) legible and intact?	Yes	No	Not Applicable
#10 Sample matrix properties agree with Chain of Custody?	Yes	No	
#11 Containers supplied by ELQT?	Yes	No	
#12 Samples in proper container/ bottle?	Yes	No	See Below
#13 Samples properly preserved?	Yes	No	See Below
#14 Sample bottles intact?	Yes	No	
#15 Preservations documented on Chain of Custody?	Yes	No	
#16 Containers documented on Chain of Custody?	Yes	No	
#17 Sufficient sample amount for indicated test(s)?	Yes	No	See Below
#18 All samples received within sufficient hold time?	Yes	No	See Below
#19 Subcontract of sample(s)?	Yes	No	Not Applicable
#20 VOC samples have zero headspace?	Yes	No	Not Applicable

Variance Documentation

Contact:

Contacted by:

Date/ Time:

Regarding:

Corrective Action Taken:



Check all that Apply

☐
☐
☐

See attached e-mail/ fax

Client understands and would like to proceed with analysis

Cooling process had begun shortly after sampling event



Sample ID	Sample Date	Sample Type	Depth	BTEX	TPH (GRO)	TPH (DRO)	TPH (TOTAL)
	4/17/2008	Grab/Auger	5'	0.1141	136.0	708.0	844.0
	4/17/2008	Grab/Auger	6'	0.0838	74.9	219.0	293.9
	4/17/2008	Grab/Auger	7'	ND	ND	23.6	23.6
GS/Comp-001	7/9/2008	Grab/Auger	5'				ND
GS/Comp-002	7/9/2008	Grab/Auger	6'				ND
GS/Comp-003	7/9/2008	Grab/Auger	7'				ND

Site Ranking is Ten (10). Depth to Ground Water 50-99' (approx. 65'). All results are ppm.



Mescalero ARL State #1

Section 2, T10S-R32E

Lea County, NM

EXHIBIT
Sample Diagram (Not to Scale)

Prepared by Robert Asher
Environmental Regulatory Agent
July 9, 2008