District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

JAN 167119 Revised October 10, 2003

HOBBSOCD Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

						OPERA	TOR	II 🔯 Ir	✓ Initial Report ☐ Final Report		
Name of Company – EverQuest Energy Corporation						Contact - Te	erry Duffey				
Address – 10 Desta Drive, Suite 300-E, Midland, TX 79705						Telephone No. – 432-686-9790					
Facility Name – Schooner B # 2						Facility Type – Producing Well					
Surface Owner – State of New Mexico Mineral Owner						Lease No.					
LOCATION						NOF RELEASE			(50:1		
Unit Letter	Section	Township	Range	Feet from the		/South Line		East/West Lir	 		_
H	17	16S	32E						Lea		
Latitude32.92260 N Longitude103.78150 W											
NATURE OF RELEASE											
Type of Release - Drilling Fluids						Volume of Release Volume Recovered					_
Source of Release – Compromised Pit Liner						Date and H unknown	our of Occurrence	Date a	Date and Hour of Discovery 6/11/08 7:30 AM		
Was Immediate Notice Given?						If YES, To Whom?					
☐ Yes ☒ No ☐ Not Required											
By Whom?						Date and Hour					
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*										 	
		,									
Describe Cause of Problem and Remedial Action Taken.*											
6/9/08 – Initial delineation was conducted with a backhoe, samples were taken and sent to Cardinal Laboratories for analysis											
Describe Area Affected and Cleanup Action Taken.* RP# 2051-											
API # 30-025-37921											
All impacted material will be removed to below acceptable MCL's and disposed of at a disposal facility;											
A 12 ml liner will be installed and original drilling pit material will be buried in place, capped with a 20 ml liner, and covered with 3' of backfill material											
to grade.		•									
T.1 1	6 1 11 .					1 1		1 1 1 1 1	30.60	GD 1 1	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Brym on behalf of							OIL CONS	FRVATIC	N DIVISIO	J	۲
Simon Free Const Free							<u>OIL COIL</u>	<u>DICTIFU</u>	71, 21, 15101		
Signature: Ever Quest Energy						Envisol	HER	^			
Printed Name: Jerry Brigon						Approved by	District Supervisor		some sulla		
Title: 1	~ \ta hc	nmed) A.	rent		Approval Date	e: 1.16.09	Expirati	on Date: 3.1	L ·09	
E-mail Addre	ess: ir	PUM	Quer.	in on . net	_	Conditions of			Attached		
Date:	16/00		Phone:	390-614	9	CIEN.	10 L5E-	SUDMIT	IRPA	+2051	
		`	-	,			.141 w/ Doc		2 4 <i>8 4</i> 9	3.16.09	
						-	,			•	