

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

RECEIVED

OCT 14 2008

HOBBS

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company OXY USA	Contact Kelton Beaird	
Address 102 S Main Carlsbad, NM 88220	Telephone No. (O) 505-887-8337 C) 575-390-1903	
Facility Name Corbin Queen 404	Facility Type Injection Well	
Surface Owner BLM	Mineral Owner	Lease No.

LOCATION OF RELEASE

API # 30.025.29739

Unit Letter K	Section 9	Township 18S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 20bbls	Volume Recovered 10bbls
Source of Release Injection line valve	Date and Hour of Occurrence	Date and Hour of Discovery 10-7-08 @ 3:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM) Larry Johnson (NMOCD)	
By Whom? Kelton Beaird (HES Oxy)	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

WTR < 25'
SENSITIVE AREA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A valve on the injection line inside a valve box leaked causing the box to fill up and overflow into the pasture. A vac-truck was called.

Describe Area Affected and Cleanup Action Taken.*

The area affected approx. 20' X 20' and a small area a couple of inches wide by 100' long (where it streamed). This area will be delineated and a work plan will be submitted for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird	Approved by District ENVIRONMENTAL ENGINEER	
Title: HES Specialist	Approval Date: 10.17.08	Expiration Date: 12.17.08
E-mail Address: kelton_beaird@oxy.com	Conditions of Approval:	
Date: 10-10-08	Submitted Final C-141 by Attached <input type="checkbox"/> IRP# 1985	

* Attach Additional Sheets If Necessary

FGRL 0903525775