

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

APR 22 2009**HOBBSOCD**

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action**OPERATOR**
☒ Initial Report ☐ Final Report

Name of Company	NADEL AND GUSSMAN HEYCO, LLC	Contact	Keith Cannon or Tammy R. Link
Address	PO Box 1936, Roswell 88202-1936	Telephone No.	(505) 623-6601
Facility Name	Young Deep Unit #4	Facility Type	

Surface Owner	USA	Mineral Owner	State of New Mexico	Lease No.	064009-D
---------------	-----	---------------	---------------------	-----------	----------

LOCATION OF RELEASE API# 30.025.27300.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	9	18S	32E	1980'	N	660'	E	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	- 5 bbls of oil	Volume of Release	5 bbls	Volume Recovered	1
Source of Release		Date/Hour of Release	4/21/09 10:30	Date/Hour Discovered	4/21/09 10:30a
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson w/Hobbs OCD		
By Whom?	Keith Cannon	Date and Hour	2:00 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

WATER @ 45'

Describe Cause of Problem and Remedial Action Taken.*



After hot watering well the valve coming from the 8 5/8" csg head blew out. Dug out well head and replaced nipples and valve 13 3/8 head and 8 5/8 head.

Describe Area Affected and Cleanup Action Taken.*

Remediation clean-up, will be spraying and rip up soil and spraying micro blaze and water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	ENV ENGR	
Printed Name: Tammy Link	Approved by District Supervisor: 	
Title: Engineering Tech	Approval Date: 05/01/09	Expiration Date: 06/30/09
E-mail Address: tlink@heycoenergy.com	Conditions of Approval: SUBMIT FINAL C-141 BY	
Date: 4-21-09 Phone: (505)623-6601	Attached <input type="checkbox"/> IRP-09.5.2167	

* Attach Additional Sheets If Necessary

FGRL 0912155621