

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company OXY USA	Contact Kelton Beaird
Address 102 S Main Carlsbad, NM 88220	Telephone No. (O) 505-887-8337 C) 575-390-1903
Facility Name Central Corbin Queen Unit	Facility Type Water Station

Surface Owner BLM	Mineral Owner	Lease No.
-------------------	---------------	-----------

LOCATION OF RELEASE

NEARBY WELL CENTRAL CORBIN QUEEN 205
API # 30-025-29453-00-00

Unit Letter K	Section 4	Township 18S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------



Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50bbls	Volume Recovered 40bbls
Source of Release Tank Battery	Date and Hour of Occurrence 3-8-09 8:00pm	Date and Hour of Discovery 3-8-09 8:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson-NMOCD (left message)	
By Whom? Kelton Beaird Oxy HES	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* WATER @ 48'		
Describe Cause of Problem and Remedial Action Taken.* Tank level filled to high causing the tank to run over		
Describe Area Affected and Cleanup Action Taken.* Vac-Truck was called to pick standing fluid up. Area will be assessed for damages and a clean-up plan will be submitted to NMOCD and BLM for approval.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by: ENV EGRR District Supervisor: 	
Printed Name: Kelton Beaird	Approval Date: 03/13/09	Expiration Date: 05/12/09
Title: HES Specialist	Conditions of Approval: SUBMIT FINAL C-141 BY 05/12/09	
E-mail Address: kelton_beaird@oxy.com	Attached <input type="checkbox"/>	
Date: 3-10-09	1RP-09.3.2119	

* Attach Additional Sheets If Necessary

FGRL 0915935995