

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JUN 05 2009
HOBBSOC

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Seely Oil Company	Contact	David L. Henderson
Address	815 W. 10 th St., Ft. Worth, TX 76102	Telephone No.	817-332-1377
Facility Name	EK Penrose Sand Unit #901	Facility Type	
Surface Owner	Federal	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	20	18S	34E	1650	South	330	West	Lea County

Latitude _____ Longitude _____ API# 30-025-34880-00-00

NATURE OF RELEASE

Type of Release	Salt water	Volume of Release	15 bbls	Volume Recovered	10 bbls
Source of Release	Injection line	Date and Hour of Occurrence	7:00 p.m. 5/15/09	Date and Hour of Discovery	7:30 p.m. 5/14/09
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD office - left message		
By Whom?	Mike Frazier	Date and Hour	7:45 a.m. 5/15/09		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

WATER @ 85'



Describe Cause of Problem and Remedial Action Taken.*

Injection line broke. Approximately 15 bbls of saltwater escaped and affected an area of approximately 10' wide x 120' on one side of the lease road and 11' x 125' on the other side of the road.

Describe Area Affected and Cleanup Action Taken.*

Line was repaired. The affected soil has been removed and will be replaced with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: David L. Henderson	Approved by:  District Supervisor	
Title: Executive Vice President	Approval Date: 06/08/09	Expiration Date: 08/07/09
E-mail Address: dhenderson@seelyoil.com	Conditions of Approval: DELINEATE AND REMEDIATE TO CLEAN UP USING NMOCD CLEAN UP GUIDELINES FOR	Attached <input type="checkbox"/>
Date: 06/03/2009 Phone: 817-332-1377		IRP-09-6-2193

* Attach Additional Sheets If Necessary

FGRW0915955153

RELEASES WHERE GW IS BETWEEN
50-99' BELOW GROUND SURFACE,
SUBMIT FINAL C-141 BY 08/07/09.