

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	John W. Gates
Address	3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No.	505.391.3158
Facility Name	MCA 2A Header 3" Fiberglass Trunk Line	Facility Type	Oil and Gas

Surface Owner	Federal	Mineral Owner	Federal	Lease No	LC-060199A
---------------	---------	---------------	---------	----------	------------

NEARBY WELL #156 - API# 30-025-00768-00-00

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	29	17S	32E					Lea

Latitude 32 48.461 Longitude 103 47.082

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Crude Oil & Produced Water	22bbl (1oil, 21water)	(0oil, 0water)
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Hole in 3" Fiberglass Trunk Line		
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Mark Whitaker	
By Whom? Jesse Sosa	Date and Hour 7/4/09 0930	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

GW @ 175'



Describe Cause of Problem and Remedial Action Taken.*

3" Fiberglass Trunkline failed due to internal/external corrosion. Temporary repairs were made with a line clamp until failed section of line can be replaced

Describe Area Affected and Cleanup Action Taken.*

100' X 240' X 1" area of sandy pasture land with no livestock present. Spill site will be remediated in accordance with an agreement with NMOCD and BLM

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	ENV ENGINEER	
Title: HSER Lead	Approved by District Supervisor: 	
E-mail Address: John.W.Gates@conocophillips.com	Approval Date: 07/07/09	Expiration Date: 09/08/09
Date: 7/8/09 Phone: 505.391.3158	Conditions of Approval: DELIVERATE TO CLEAN + 1. SUBMIT FINAL C-141 BY	Attached <input type="checkbox"/>
		IRP-09.7.2223

- Attach Additional Sheets If Necessary

FGRL0919440241