

JUL 27 2009

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-25141

Release Notification and Corrective Action

NMLB0922331732

246368

OPERATOR

Initial Report

Final Report

Name of Company	Basic Energy Service	Contact	Jerry Hanway
Address	PO Box 1747 CARLSBAD 88221	Telephone No.	575-234-1778
Facility Name	Belco #1	Facility Type	Salt Water Disposal

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	20	235	28E	600 <del>FEET</del>	FWL	2200	FWL	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	lighting strike on tank	Volume of Release	1000 Bbl	Volume Recovered	850 Bbl
Source of Release	fire burnt down tanks	Date and Hour of Occurrence	9 PM	Date and Hour of Discovery	9 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD by Phone		
By Whom?	Rolando Ortiz	Date and Hour	July 16 1200 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\* lighting strike to gunbarrel - tanks caught fire burning then releasing plw from tanks - all liquid was picked up affected soil was removed and taken to CRI

Describe Area Affected and Cleanup Action Taken.\* All area was cleaned and soil removed approx. 250 ft by 275 ft area was cleaned

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	Jerry Hanway	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Jerry Hanway	Approved By:	Mike Brannan
Title:	yard Supt	Approval Date:	AUG 11 2009
E-mail Address:		Expiration Date:	
Date:	7-23-09	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Phone:			

\* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 9/11/2009

2AP-327

sally.phillips@basicenergyservices.com



New Mexico Energy, Minerals and Natural Resources Department

**Bill Richardson**  
Governor

**Joanna Prukop**  
Cabinet Secretary

**Mark Fesmire**  
Division Director  
Oil Conservation Division



Basic Energy Services  
PO Box 1747  
Carlsbad, NM 88221  
ATTN: Jerry Hanway

August 11, 2009

Reference: Belco 001 API: 30-015-25141 E-20-23s-28e Eddy County, New Mexico

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an initial report Form C-141 reporting a release of produced fluids at or near the above referenced well site. The release reportedly occurred on or about July 15, 2009. Please submit a corrective action work plan proposal (plan) for remediation and/or removal of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD rules, regulations and guidelines.

A publication is available to you on the OCD website to aid in formulation of this plan. The publication may be found as follows:

<http://www.emnrd.state.nm.us/ocd>

Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 Office not later than **September 2, 2009**. Please include any remedial or clean up actions that may have already been performed at the site.

Clean up/remediation requirements may be subject to other federal, state, local laws and/or regulations.

Sincerely,

Mike Bratcher  
NMOCD District 2  
1301 W. Grand Ave.  
Artesia, NM 88210  
575-748-1283 Ext.108  
[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)

2RP-327

email: [sallyphillips@basicenergyservices.com](mailto:sallyphillips@basicenergyservices.com)

