

AUG 14 2009 *mk*

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of formState of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

30-015-26134

## Release Notification and Corrective Action

nmlc 0923230505

## OPERATOR

X Initial Report ☐ Final Report

Name of Company SANDLOTT ENERGY 154329	Contact JACKIE BREWER
Address PO BOX 711 Lovins Ave NM 88260	Telephone No. 575-631-4592
Facility Name RESLER YATES # 381	Facility Type ACTIVE PRODUCTION WELL HEAD <i>BATTERY</i>
Surface Owner NMSLO	Mineral Owner
Lease No. 30-015-26134	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	32	18S	28E	1884	NORTH	1394	EAST	EDDY

Latitude *N32°42'21.89"* Longitude *W104°01'37.65"*

## NATURE OF RELEASE

Type of Release PROD. WATER	Volume of Release 3 BBLs	Volume Recovered 3 BBLs
Source of Release	Date and Hour of Occurrence 08/07/09 APPROX. 3AM	Date and Hour of Discovery 08/07/09 9:00AM
Was Immediate Notice Given? X Yes <input type="checkbox"/> No X Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom?	Date and Hour 08-07-09 9:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* TANK RAN OVER DUE TO EXCESS WATER		
Describe Area Affected and Cleanup Action Taken.* 3BBLs WATER AROUND TANK INSIDE DIKE. HAUL TRUCKING SUCKED WATER UP FROM GROUND		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>J. Brewer</i>	OIL CONSERVATION DIVISION	
Printed Name: Jackie Brewer	Approved by <i>Mike Bratcher</i>	
Title: Owner Operator	Approval Date: AUG 20 2009	Expiration Date:
E-mail Address: Brewer.212@AOL.Com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 8-14-09 Phone:		

\* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL BY: *Proposal rec'd 8/14/09*

2 RA-328

AUG 14 2009 *ck*


TO: MIKE BRATCHER

AUG 14, 2009

FROM: JACKIE BREWER D/B/A SANDLOTT ENERGY

RE: RESLER YATES 381 BATTERY  
LEASE 30-015-26134 G 32-18S-28E- 1884N 1394E EDDY  
SITE RANKING 0

PLAN FOR CLEAN UP SPILL ON RESLER YATES # 381  
REMOVAL OF 2 210 TANKS AND PUMP  
ALL LINES DUG UP. CONTAMINATED SOIL REMOVED AND HAULED TO CRI  
LAY 28 BY 28 BASE MATERIAL 4 COVER WITH 40MM PLASTIC, COVER PLASTIC WITH  
BASE MATERIAL THEN TOP WITH GRAVEL  
PLACE PUMP IN PLASTIC CONTAINER SET TANKS  
BUILD 30 INCH HIGH DIKE AROUND TANKS AND PUMP

  
\_\_\_\_\_  
JACKIE BREWER D/B/A SANDLOTT ENERGY



# New Mexico Energy, Minerals and Natural Resources Department

**Bill Richardson**  
Governor

**Joanna Prukop**  
Cabinet Secretary

**Mark Fesmire**  
Division Director  
Oil Conservation Division



Sandlott Energy  
PO Box 711  
Lovington, NM 88260  
ATTN: Jackie Brewer

August 20, 2009

Reference: Resler Yates State 381 30-015-26134 G-32-18s-28e Eddy County, New Mexico

OCD Reference: **2RP-328**

Mr. Brewer,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an Initial Report Form C-141 and remediation work plan for proposed corrective actions to be taken to clean up a produced fluids release that occurred at the above referenced well site on or about August 7, 2009. The release was due to a tank overflow in a recently constructed, bermed tank battery.

The work plan proposal is approved with the following stipulations and/or conditions:

- Notify OCD 48 hours prior to commencement of remediation activities.
- Notify OCD 48 hours prior to obtaining samples where analyses of samples obtained are to be submitted to OCD.
- Provide a site ranking and target remediation levels for contaminants, per OCD Guidelines.
- After removal of visibly identifiable contaminated materials, and prior to installing liner in battery area, confirmation samples are to be obtained from all areas affected by this release. Samples are to be taken with proper chain of custody to an OCD approved lab and tested for, at a minimum, BTEX, TPH and Chloride constituents. OCD review of analytical data and approval is required prior to liner installation.
- Remediation activities, to include submittal of a Final Report C-141, are to be completed not later than September 20, 2009.

OCD understands that, based on our meetings on site and in OCD office that removal of vessels and equipment, and, excavation of impacted materials has already commenced at this site.


Please be advised that OCD approval does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.



August 20, 2009  
Page 2

If you have any questions or concerns, please contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Mike Bratcher", written in a cursive style.

Mike Bratcher  
NMOCD District 2  
1301 W. Grand Ave.  
Artesia, NM 88210  
575-748-1283 Ext.108  
[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)

Distribution: email to [Brewer212@AOL.com](mailto:Brewer212@AOL.com)

Certified USPS to listed address 8/20/2009

## Bratcher, Mike, EMNRD

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Thursday, August 20, 2009 1:49 PM  
**To:** 'brewer212@aol.com'  
**Subject:** Resler Yates State 381  
**Attachments:** Sandlott Energy 8.20.09.doc

Jackie,

Attached is the approval and conditions of approval for remediation at the Resler Yates Battery. If you have any questions, give me a call.

Thanks,

Mike Bratcher  
NMOCD District 2  
575-748-1283 Ext.108

**Bratcher, Mike, EMNRD**

---

**From:** postmaster@state.nm.us  
**Sent:** Thursday, August 20, 2009 1:50 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** Delivery Status Notification (Relay)  
**Attachments:** ATT4365141.txt; Resler Yates State 381

This is an automatically generated Delivery Status Notification.

Your message has been successfully relayed to the following recipients, but the requested delivery status notifications may not be generated by the destination.

[brewer212@aol.com](mailto:brewer212@aol.com)