

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1000 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Targa Midstream Services L P	Contact: Tim Jordan or Ralph England
Address: PO Box 1689 Lovington, NM 88260	Telephone No. (575) 396-3221
Facility Name: Saunders Plant	Facility Type: Gas Processing Plant

Surface Owner: Etcheverry (Middle)	Mineral Owner:	Lease No.
---------------------------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter A	Section 1	Township 15S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N33.05005 Longitude W103.56204

NATURE OF RELEASE

Type of Release: Natural Gas and Produced Liquid	Volume of Release: Approximately 14.15 mcf of raw gas and unknown amount of Produced liquid.	Volume Recovered: 0
Source of Release: Hole in 4" Pipeline with 14 psig of pressure passing about 70mcf of natural gas with containing 2500ppm of H2S. Line has been taken out of service.	Date and Hour of Occurrence: Not sure	Date and Hour of Discovery 05/05/09 Line monitor aircraft discovered leak.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken. *

A 4 inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Line was repaired with clamp. Line has been taken out of service to prevent future contamination. Contaminated soil will be hauled to an approved landfill. Area will be cleaned to meet OCD guidelines. Line monitor aircraft discovered leak.

Describe Area Affected and Cleanup Action Taken.*

Targa has excavated the contaminated area from leak to include runoff. Contaminated soil has been hauled to an approved landfarm. Targa purchased soil from Landowner to fill excavation after approval to close

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by ENV ENGINEER: District Supervisor: 	
Title: Training Specialist	Approval Date: 09/26/09	Expiration Date:
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/06/09 Phone: (432) 688-0546		IRP-09-6-2201

* Attach Additional Sheets If Necessary

RECEIVED

District I
1625 N. French Dr., Hobbs. NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 11 2009 Form C-141
Revised October 10, 2003

HOBBSOCD
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services L P	Contact: Tim Jordan or Ralph England
Address: PO Box 1689 Lovington, NM 88260	Telephone No. (575) 396-3221
Facility Name: Saunders Plant	Facility Type: Gas Processing Plant

Surface Owner: Etcheverry (Middle)	Mineral Owner:	Lease No.
---------------------------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter A	Section 1	Township 15S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N33.05005 Longitude W103.56204**NATURE OF RELEASE**

Type of Release: Natural Gas and Produced Liquid	Volume of Release: Approximately 14.15 mcf of raw gas and unknown amount of Produced liquid.	Volume Recovered: 0
Source of Release: Hole in 4" Pipeline with 14 psig of pressure passing about 70mcf of natural gas with containing 2500ppm of H2S. Line has been taken out of service.	Date and Hour of Occurrence: Not sure	Date and Hour of Discovery 05/05/09 Line monitor aircraft discovered leak.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4 inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Line was repaired with clamp. Line has been taken out of service to prevent future contamination. Contaminated soil will be hauled to an approved landfill. Area will be cleaned to meet OCD guidelines. Line monitor aircraft discovered leak.

Describe Area Affected and Cleanup Action Taken.*

Targa will excavate the contaminated area from leak to include runoff. Contaminated soil will be hauled to an approved landfarm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by District Supervisor: <i>[Signature]</i>	
Title: Training Specialist	Approval Date: <u>6.11.09</u>	Expiration Date: <u>9.11.09</u>
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/09/09 Phone: (432) 688-0546		IRP* 09.6.2201

* Attach Additional Sheets If Necessary



FGR 0916355498

ETCHEVERRY MIDDLE

SAMPLE DATE	SAMPLE I.D.	SOIL STATUS	TPH GRO	TPH DRO	CHLORIDE
6/8/2009	#1 Clamp	Excavated	368	2000	288
6/8/2009	#2 North Clamp	Excavated	<10	24.8	<16
7/27/2009	#3 Clamp	In Situ	<10	<10	<16
7/27/2009	#4 North Clamp	In Situ	<10	<10	<16

8/6/2009


ETCHEVERRY MIDDLE



#1 #3




Clamp





PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240



ANALYTICAL RESULTS FOR
TARGA
ATTN: DON EMBREY
6 DESTA DRIVE, SUITE 3300
MIDLAND, TX 79705
FAX TO: (432) 688-0552

Receiving Date: 06/08/09
Reporting Date: 06/10/09
Project Number: NOT GIVEN
Project Name: NOT GIVEN
Project Location: ECHEBERRY

Sampling Date: 06/08/09
Sample Type: SOIL
Sample Condition: INTACT @ 12°C
Sample Received By: ML
Analyzed By: AB/HM

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/kg)	DRO (>C ₁₀ -C ₂₈) (mg/kg)	*Cl ⁻ (mg/kg)
		06/09/09	06/09/09	06/09/09
H17578-1	W. EX WEST	<10.0	23.9	<16
H17578-2	W. EX MIDDLE	12.6	3,220	1,020
H17578-3	W. EX EAST	361	995	160
H17578-4	W. EX COMPOSITE	<10.0	356	672
H17578-5	M. EX CLAMP	368	2,000	288
H17578-6	M. EX NORTH CLAMP	<10.0	24.8	<16
H17578-7	E. EX CLAMP	17.2	364	192
Quality Control		538	539	490
True Value QC		500	500	500
% Recovery		108	108	98.0
Relative Percent Difference		3.8	0.8	2.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl⁻: Std. Methods 4500-Cl⁻B

*Analyses performed on 1:4 w:v aqueous extracts. Reported on wet weight.

Surrogate for H17578-1 outside historical limits due to matrix interference.

Chemist

Date

H17578 TCL TARGA

PLEASE NOTE **Liability and Damages** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



CARDINAL LABORATORIES

101 East Marland, Hobbs, NM 88240

(575) 393-2326 Fax (575) 393-2476

Page ____ of ____

Company Name: TARGA Project Manager: Don Embrey Address: 6 Desta Drive Suite 3300 City: M. OLANO State: TX Zip: 79705 Phone #: 432-688-0546 Fax #: 432-688-0552 Project #: Project Owner: Project Name: Project Location: Echegaray Sampler Name: Don Embrey				BILL TO P.O. #: Company: TARGA Attn: Address: P.O. Box 1689 City: LOUINGTON State: NM Zip: 88260 Phone #: Fax #:				ANALYSIS REQUEST																				
FOR LAB USE ONLY				MATRIX				PRESERV.		SAMPLING																		
Lab I.D.	Sample I.D.	(G)RAB OR (C)OMP	# CONTAINERS	GROUNDWATER	WASTEWATER	SOIL	OIL	SLUDGE	OTHER	ACID/BASE	ICE / COOL	OTHER	DATE	TIME														
H1758-1	W. Ex West		-			✓							6-8-09	10:45	✓	✓												
-2	W. Ex MIDDLE		-			✓								10:45	✓	✓												
-3	W. Ex EAST		-			✓								10:45	✓	✓												
-4	W. Ex Composite		-			✓								10:45	✓	✓												
-5	M. Ex Clamp		-			✓								11:00	✓	✓												
-6	M. Ex North Clamp		-			✓								11:00	✓	✓												
-7	E. Ex Clamps		-			✓								11:15	✓	✓												

PLEASE NOTE: Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the client for the analyses. All claims including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise.

Sampler Relinquished: Date: Time:		Received By: Date: 6-8-09 Time: 2:15		Phone Result: <input type="checkbox"/> No Add'l Phone #: Fax Result: <input type="checkbox"/> No Add'l Fax #: REMARKS:	
Relinquished By: 		Received By: 			
Delivered By: (Circle One) Sampler - UPS - Bus - Other:		Temp: 12°C Sample Condition: Cool Intact <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> No CHECKED BY: (Initials) 			

† Cardinal cannot accept verbal changes. Please fax written changes to 575-393-2476.

* samples in cooler w/ blue packs

**ARDINAL
LABORATORIES**PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

July 28, 2009

Don Embrey
Targa Resources
6 Desta Drive Suite 3300
Midland, TX 79705

Re: Etcheverry

Enclosed are the results of analyses for sample number H17874, received by the laboratory on 07/27/09 at 12:15 pm.


Cardinal Laboratories is accredited through Texas NELAP for:

Method SW-846 8021	Benzene, Toluene, Ethyl Benzene, and Total Xylenes
Method SW-846 8260	Benzene, Toluene, Ethyl Benzene, and Total Xylenes
Method TX 1005	Total Petroleum Hydrocarbons

Certificate number T104704398-08-TX. Accreditation applies to solid and chemical materials and non-potable water matrices.

Total Number of Pages of Report: 3 (includes Chain of Custody)

Sincerely,


Celey D. Keene
Laboratory Director

This report conforms with NELAP requirements.



ARDINAL LABORATORIES

PHONE (575) 383-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR

TARGA

ATTN: DON EMBREY

6 DESTA DRIVE SUITE 3300

MIDLAND, TX 79705

FAX TO (432) 688-0552

Receiving Date: 07/27/09

Reporting Date: 07/28/09

Project Number: NOT GIVEN

Project Name: ETCHEVERRY

Project Location: NOT GIVEN

Sampling Date: 07/27/09

Sample Type: SOIL

Sample Condition: INTACT @ 7°C

Sample Received By: NF

Analyzed By: AB/HM

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/kg)	DRO (>C ₁₀ -C ₂₈) (mg/kg)	*Cl (mg/kg)
------------	-----------	--	--	----------------

ANALYSIS DATE		07/28/09	07/28/09	07/28/09
H17874-1	W. ETCHEVERRY CLAMP	<10.0	22.6	< 16
H17874-2	W. ETCHEVERRY W. END	<10.0	<10.0	< 16
H17874-3	M. ETCHEVERRY CLAMP	<10.0	<10.0	< 16
H17874-4	M. ETCHEVERRY N. SIDE	<10.0	<10.0	< 16
H17874-5	E. ETCHEVERRY	<10.0	14.4	84
H17874-6	FAR E. ETCHEVERRY	<10.0	42.6	< 16
Quality Control		533	586	500
True Value QC		500	500	500
% Recovery		107	117	100
Relative Percent Difference		19.4	4.5	2.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M, Cl: Std. Methods 4500-ClB

*Analyses performed on 1:4 w/v aqueous extracts. Reported on wet weight

Surrogate for DRO on H17874-3 and 4 was outside historical limits due to matrix interference.


 Chemist


 Date

H17874 TCL TARGA

PLEASE NOTE: **Liability and Damages.** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

**CARDINAL LABORATORIES**

101 East Marland, Hobbs, NM 88240

(575) 393-2326 Fax (575) 393-2476

Page ____ of ____

Company Name: TARGA		BILL TO		ANALYSIS REQUEST																
Project Manager: Don Embrey		P.O. #:																		
Address: 6 Desta Drive		Company: TARGA																		
City: MIDLAND State: TX Zip: 79705		Attn:																		
Phone #: 432-557-9831 Fax #: 432-688-0552		Address: P.O. Box 1689																		
Project #: Etcheverry Project Owner:		City: Louington																		
Project Name: Etcheverry		State: NM Zip: 88260																		
Project Location:		Phone #:																		
Sampler Name: Don Embrey		Fax #:																		
Lab ID	Sample ID	GRAB OR (C)OMP	# CONTAINERS	MATRIX GROUNDWATER WASTEWATER SOIL OIL SLUDGE OTHER	PRESERV. ACID/BASE ICE / COOL OTHER	SAMPLING DATE	TIME													
H178741	W. Etcheverry Clamp					7-27-01	10 AM	x												
-2	W. Etcheverry W. END						10 AM	x												
-2	M. Etcheverry Clamp						10:05 AM	x												
-4	M. Etcheverry N. Side						10:05 AM	x												
-5	E. Etcheverry						10:10 AM	x												
-6	FAR E. Etcheverry						10:30 AM	x												

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising under this contract or for shall be limited to the amount paid by the client for the analyses. All claims, including those for negligence and any other causes whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of this applicable service. In no event shall Cardinal be liable for incidental or consequential damages including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise.

Sampler Relinquished By: Don Embrey		Date: 7-27-01	Received By: [Signature]	Phone Result: <input type="checkbox"/> No Add'l Phone #:
Relinquished By:		Date: 7-27-01	Received By:	Fax Result: <input type="checkbox"/> No Add'l Fax #:
Time: 12:15 PM				REMARKS:
Delivered By: (Circle One) Sampler - UPS - Bus - Other:		Temp. 7°	Sample Condition Cool Intact <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> No <input type="checkbox"/> No	CHECKED BY: (Initials)

on ice, cooling process begun @ 10:00 AM per customer

† Cardinal cannot accept verbal changes. Please fax written changes to 575-393-2476.


#26

MIDDLE

07/27/2009



MIDDLE



07/27/2009

#1 MIDDLE (Looking West)



06/08/2009

#2 MIDDLE (Looking East)




06/08/2009

#3 MIDDLE (Looking East)





06/08/2009



06/08/2009



06/08/2009