State of New Mexico RECEIVED

Oil Conservation Division

OCT 1 3 2009

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

2205 St Fran	icis Dr , Sant	a re, NM 8750:	5	Sant	outh St. Fran a Fe, NM 87	505		~~~~	9			side of for	
			Rele	ase Notificat	tion and C	orrecti	ve A	ction					
					OPERA	TOR		\boxtimes	Initia	al Report		Final Rep	
Name of Company PRIDE ENERGY COMPANY					Contact M	Contact MATTHEW L. PRIDE							
Address P.O. BOX 701950, TULSA, OK 74170-1950 Facility Name SOUTH FOUR LAKES UNIT #13 SWD						Telephone No. 918-524-9200 Facility Type SALT WATER DISPOSAL WELL							
Surface Owner A.D. JONES ESTATE, INC. Mineral Owner					ner STATE OF	er STATE OF NEW MEXICO Lease No. E-2064; 937-2; E-59 API #: 30-025-36528							
				LOCAT	ION OF RE	LEASE							
Unit Letter	Section	Township	Range	Feet from the N	lorth/South Line	Feet from	m the	East/Wes	st Line	County			
L	1	125	34E	1830	SOUTH	735		WEST	-		LEA ·		
<u></u>	• • • • • • • • • • • • • • • • • • •	I	La	titude	~ .	de							
					RE OF REL								
Lype of Rele					Volume o	f Release				Recovered			
source of Re	lease SAL	T WATER T	ANK		Date and H Approx 1	lour of Occu 00 a m	irrence 10		ate and I m	Hour of Disco	overy 10/	1/09 9 00	
Was Immedi	ate Notice (Yes 🗌	No 🗌 Not Requ	If YES, T		Geoffrey			D) Hobbs D	District		
By Whom?		Hour 10/1.				ST							
Was a Water	course Read]Yes 🛛	No	If YES, V	'olume Imp	pacting th	he Waterco	ourse.				
		L		110	1								
f a Waterco	urse was Im	pacted, Descr	ibe Fully.*	6									
Describe Cat	use of Probl	em and Reme	dial Action		d. Head switch ha	us been rep	laced.						
Describe Cai Head switch	use of Probl	em and Reme ic shut down o	dial Action	n Taken.* er tank malfunctione	d. Head switch ha	ıs been rep	laced.		ഹ	NGZ	.5		
Describe Cai Head switch	use of Probl	em and Reme	dial Action	n Taken.* er tank malfunctione	d. Head switch ha	is been rep	laced.		<u>G</u>	NGZ	.5 1		
Describe Cau Head switch Describe Are Approximate diked area ar	use of Probl on automat a Affected sly 250 bbls ound the ta	em and Reme ic shut down o and Cleanup A . of saltwater nk battery A	dial Action on saltwate Action Tak were conta vac. truck	n Taken.* er tank malfunctione	l area around the	tank batter	y and ap		ely 25 bt	bls. saltwate			
Describe Cat Head switch Describe Are Approximate diked area ar of approxima of approxima I hereby cert regulations a public health should their of or the enviro	use of Probl on automat ea Affected ely 250 bbls round the ta ately 75bbls offy that the ll operators or the envi operations h nment. In a	em and Reme ic shut down of and Cleanup A . of saltwater nk battery A 5 in an offsite unformation g are required to ronment The bave failed to	dial Action on saltwate Action Tak were conta vac. truck commerci- tiven above to report ar acceptanc adequately DCD accep	n Taken.* er tank malfunctioned en.* uned inside the diked picked up the saltwa	d area around the ter and put appro- e to the best of m ase notifications by the NMOCD r ediate contamina	tank batter ximately 20 y knowledg and perform narked as " tion that po ve the oper	y and ap 00 bbls. I ge and ur n correct Final Re ose a thre ator of r	back into t nderstand t tive action eport" does eat to grou esponsibil	the saltw that purs is for rel s not rel nd water ity for c	bls. saltwate vater tank and suant to NN leases which ieve the ope r, surface w compliance	nd prope 10CD ru n may er erator of vater, hun with any	erly dispos ules and idanger Thability man health	
Describe Cat Head switch Describe Are Approximate diked area ar of approxima of approxima I hereby cert regulations a public health should their or the enviro federal, state	use of Probl on automat ea Affected ely 250 bbls round the ta ately 75bbls of that the ll operators or the envi operations h nment. In a , or local lar	em and Reme ic shut down of and Cleanup A of saltwater nk battery A is in an offsite information g are required to ronment The bave failed to addition, NMC	dial Action on saltwate Action Tak were conta vac. truck commerci- tiven above o report ar acceptanc adequately DCD accep ulations	n Taken.* er tank malfunctioner en.* nined inside the diked picked up the saltwa al disposal well. is true and complete id/or file certain rele e of a C-141 report l investigate and rem tance of a C-141 rep	d area around the ter and put appro- e to the best of m ase notifications by the NMOCD r ediate contamina	tank batter ximately 20 y knowledg and perform narked as " tion that po ve the oper OIL	y and ap 00 bbls. I n correct Final Re ose a thre rator of r	back into t inderstand t tive action eport" does eat to grout esponsibil SERVA	the saltw that purs is for rel s not rel nd water ity for c	bls. saltwate vater tank an suant to NM eases which ieve the ope r, surface w	nd prope 10CD ru n may er erator of vater, hun with any	erly dispos ules and idanger Thability man health	
Describe Cat Head switch Describe Are Approximate diked area ar of approxima t hereby cert regulations a bublic health should their of or the enviro federal, state	use of Probl on automat ea Affected ely 250 bbls round the ta ately 75bbls ify that the ll operators or the envi operations h ment. In a , or local law Mac By: Pro-	em and Reme ic shut down of and Cleanup A of saltwater nk battery A is in an offsite information g are required t ronment The nave failed to a iddition, NMC ws and/or regu the Products	dial Action on saltwate Action Tak were conta vac. truck commercia iven above or report ar e acceptance adequately DCD acceptance add add acceptance add add acceptance add add acceptance add add acceptance add add acceptance add add acceptance add acceptance add add acceptance add acc	n Taken.* er tank malfunctioned en.* uned inside the diked picked up the saltwa al disposal well. is true and complete dd/or file certain rele investigate and rem tance of a C-141 report <i>investigate and rem</i>	d area around the ter and put appro- e to the best of m ase notifications by the NMOCD r ediate contamina	tank batter ximately 20 and perform narked as " tion that po ve the oper <u>OIL</u> ENV EN	y and ap 00 bbls. I n correct Final Re ose a thre rator of r CONS	back into t inderstand t tive action eport" does eat to groun esponsibil SERVA	the saltw the saltw that purs s for rel s not rel nd water ity for c TION	bls. saltwate vater tank an suant to NN eases which ieve the ope r, surface w compliance DIVISI	nd prope 10CD ru n may er erator of rater, hur with any ON	erly dispos ules and idanger Thability man health	
Describe Cat Head switch Describe Are Approximate diked area ar of approxima l hereby cert regulations a bublic health should their or the enviro federal, state Signature: Printed Name	use of Probl on automat ea Affected ely 250 bbls ound the ta ately 75bbls or the envi operations h nment. In a , or local lar Mac By: Pr E: By: I	em and Reme ic shut down of and Cleanup A of saltwater nk battery A is in an offsite information g are required to ave failed to a iddition, NMC ws and/or regi	dial Action on saltwate Action Tak were conta vac. truck commerci- tiven above o report ar e acceptance adequately DCD acceptance add add acceptance add add acceptance add add acceptance add add acceptance add add acceptance add acceptance add add acceptance add add acceptance add add acceptance add acceptance add add acceptance add acceptance add add acceptance add add acceptance add add acceptance add add acceptance add add acceptance add acceptance a	n Taken.* er tank malfunctioned en.* uned inside the diked picked up the saltwa al disposal well. is true and complete dd/or file certain rele investigate and rem tance of a C-141 report <i>investigate and rem</i>	d area around the ter and put appro- e to the best of m ase notifications a by the NMOCD r ediate contamina- iort does not relie	tank batter ximately 20 y knowledg and perform narked as " tion that po ve the oper <u>OIL</u> <u>ENV EN</u> y District S	y and ap 00 bbls. I ge and ur n correct Final Re see a thre rator of n CONS	back into t inderstand t tive action eport" does eat to grout esponsibil SERVA	that purs that purs s for rel nd water ity for c TION	bls. saltwate vater tank and suant to NN leases which ieve the ope r, surface w compliance	nd properiod properiod properiod name of the name of t	erly dispos ules and idanger Thability man health other	
Describe Cat Head switch Describe Are Approximate diked area ar of approxima I hereby cert regulations a public health should their of or the enviro federal, state Signature: Printed Nam	use of Probl on automat ea Affected ely 250 bbls round the ta ately 75bbls off that the ll operators or the envi operations h mment. In a , or local lar <u>Mac</u> e: By: Pri By: I - Title:	em and Reme ic shut down of and Cleanup A and Cleanup A a of saltwater nk battery A is in an offsite information g are required to addition, NMC ws and/or regi- tude Production General Part Matthew L. I	dial Action on saltwate Action Tak were conta vac. truck commerci- tiven above o report ar e acceptance adequately DCD accep ulations $\mathcal{L}_{i} \mathcal{P}_{i}$ ton Co., In ther Pride	n Taken.* er tank malfunctioned en.* uned inside the diked picked up the saltwa al disposal well. is true and complete dd/or file certain rele investigate and rem tance of a C-141 report <i>investigate and rem</i>	d area around the ter and put appro- e to the best of m ase notifications a by the NMOCD r ediate contamina- ort does not relie Approved by Approval Da Conditions of	tank batter ximately 20 y knowledg and perform narked as " tion that po ve the oper <u>OIL</u> <u>ENV EN</u> y District S ate: 10\11	y and ap 00 bbls. 1 90	back into t inderstand t tive action eport" does eat to group esponsibil SERVA SERVA ER EX EX	that purs that purs s for rel s not rel nd water ity for c TION	bls. saltwate vater tank an suant to NM eases which ieve the ope r, surface w compliance DIVISIC	nd properiod for the property of the property	erly disposi- ules and idanger Thability man health other	
Describe Cau Head switch Describe Are Approximate diked area ar of approxima I hereby cert regulations a public health should their a or the enviro federal, state Signature: Printed Nam Title E-mail Addre	use of Probl on automat ea Affected ely 250 bbls round the ta ately 75bbls off that the ll operators or the envi operations h mment. In a , or local lar <u>Mac</u> e: By: Pri By: I - Title:	em and Reme ic shut down of and Cleanup A of saltwater nk battery A is in an offsite information g are required t ronment The bave failed to a iddition, NMC ws and/or regi the Production General Part Matthew L. I : President	dial Action on saltwate Action Tak were conta vac. truck commerci- tiven above o report ar e acceptance adequately DCD accep ulations $\mathcal{L}_{i} \mathcal{P}_{i}$ ton Co., In ther Pride	n Taken.* er tank malfunctioned en.* uned inside the diked picked up the saltwa al disposal well. is true and complete dd/or file certain rele investigate and rem tance of a C-141 report <i>investigate and rem</i>	d area around the ter and put appro- e to the best of m ase notifications a by the NMOCD r ediate contamina- iort does not relie Approved by Approval Da Conditions of CLERN 4	tank batter ximately 20 y knowledg and perform narked as " tion that po ve the oper <u>OIL</u> <u>ENV EN</u> y District S ate: 10\11	y and ap 00 bbls. 1 90	back into t inderstand t tive action eport" does eat to group esponsibil SERVA SERVA ER EX EX	that purs that purs s for rel s not rel nd water ity for c TION	bls. saltwate vater tank an suant to NM leases which ieve the ope r, surface w compliance DIVISIO	nd properiod for the formation of the fo	erly dispos ules and idanger Thability man health y other	

PRIDE ENERGY COMPANY

(918) 524-9200 + Fax (918) 524-9292 + www.pride-energy.com

Physical Address: Kensington Tower 2250 East 73rd Street, Suite 550 Tulsa, OK 74136

Mailing Address: Email Address:

P.O. Box 701950 Tulsa, OK 74170-1950 mattp@pride-energy.com

October 7, 2009

Via Certified Mail **Return Receipt #:**

91 7108 2133 3936 0786 3400

Attn.: State of New Mexico **Oil Conservation Division** 1625 N. French Dr. Hobbs, NM 88240

RECEIVED

DCT 13 2005 HOBBSUUD

RE: South 4 Lakes Unit, #13 SWD well API #: 30-025-36528 Lea County, New Mexico

Attached are 2 originals of Form C-141.

Thank you,

matthen L. Pride

Matthew L. Pride

C. New 2018 in the state of the search

. ..