

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 30 2009

HOBBSOC

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

Name of Company XTO Energy, Inc.	Contact Gene Hudson
Address 200 N. Loraine Ste.#800 Midland, Tx. 79701	Telephone No. 575-441-1634
Facility Name EMSU-B # 861	Facility Type Water Injection Trunk Line

Surface Owner Faye Kline	Mineral Owner N.M.	Lease No.
--------------------------	--------------------	-----------

LOCATION OF RELEASE

API # 30.025.12723.00.00

Unit Letter L	Section 11	Township 20 S	Range 36 E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
---------------	------------	---------------	------------	---------------	------------------	---------------	----------------	------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 200 bbl.	Volume Recovered 170 bbl.
Source of Release Fiberglass line leak	Date and Hour of Occurrence 11-25-09 10:00a.m.	Date and Hour of Discovery 11-25-09 12:00 p.m.
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? voicemail left for Jeffrey @NMOCD-Hobbs office	
By Whom? Gene Hudson	Date and Hour 11-25-09 2:20 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

GW @ 32'

Describe Cause of Problem and Remedial Action Taken.*

Failure in the fiberglass line connections-Trunk line leak area was isolated.

Describe Area Affected and Cleanup Action Taken.*

Vacuum trucks were used to remove produced water off the ground. A backhoe backdug the impacted area, to remove wet soil off the site and stock piled on plastic. The area will be remediated per NMOCD requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gene Hudson</i>	OIL CONSERVATION DIVISION	
Printed Name: Gene Hudson	ENV ENGINEER: Approved by District Supervisor: <i>Jeffrey Selinger</i>	
Title: Maintenance Foreman	Approval Date: 12/02/09	Expiration Date: 02/02/09
E-mail Address: richard_hudson@xtoenergy.com	Conditions of Approval: DELINEATE TO CLEAN + 1. SITE IS IN A SENSITIVE AREA AS GW < 50'. SUBMIT FINAL C-141	
Date: 11-30-09 Phone 575-441-1634	Attached <input type="checkbox"/>	IRP-09-12-2362

* Attach Additional Sheets If Necessary

BY 02/02/09

F8RL0933656774