

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**

JUL 28 2008

**HOBBS OIL**

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report

☐ Final Report

Name of Company - BC Operating, Inc.	Contact - Gary Stevens
Address - P.O. Box 50820 Midland TX 79710	Telephone No. - 432-894-7113
Facility Name - Cambio 31 -1	Facility Type - Producing Well
Surface Owner - Danny Watson	Mineral Owner
Lease No.(API #) - 30-025-36480	

**LOCATION OF RELEASE**

Unit Letter D	Section 31	Township 15S	Range 35E	Feet from the 1230	North/South Line North	Feet from the 1054	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude - N 32.97754

Longitude - W 103.45232

WTR 60

**NATURE OF RELEASE**

Type of Release - oil	Volume of Release 17 bbls	Volume Recovered 15 bbls
Source of Release - Storage Tank valve	Date and Hour of Occurrence unknown	Date and Hour of Discovery 7/22/08 5:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson- NMOCD	
By Whom? Jerry Brian-Brian Environmental Services, LLC	Date and Hour 7/23/08 - 6:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Oil hauler sealed valve on the tank open and a cow opened the load line valve; backhoe was moved to location to stabilize and contain liquids; the release was reported as an Emergency Response to NMOCD, an Emergency Response One-Call was conducted

Describe Area Affected and Cleanup Action Taken.\*

A vacuum truck was called to recover fluids, a backhoe is being used to remove all hydrocarbon impacted soil to nearby landfarm; all hydrocarbon impacted soil will be removed and disposed of in accordance with NMOCD regulations

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Pam Botkin	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Pam Botkin	Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Engineering Tech	Approval Date: 7-25-08	Expiration Date: 09/25/08
E-mail Address: pbotkin@usa online.net	Conditions of Approval:	
Date: 7-25-08	Phone: 432-684-9696	Attached <input type="checkbox"/> IRP 10.2.2A36

FGRL1006054880