

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

OPERATOR  Initial Report  Final Report

Name of Company	<i>Sheridan</i>	Contact	<i>Eddie Elliott</i>
Address	<i>PO BOX 34 STATE BOO DRIN PLANN, Houston TX</i>	Telephone No.	<i>575-241-7346</i>
Facility Name	<i>NUANUA</i>	Facility Type	<i>NUANUA</i>

Surface Owner	<i>STATE</i>	Mineral Owner	<i>STATE</i>	Lease No.	
---------------	--------------	---------------	--------------	-----------	--

**LOCATION OF RELEASE "C" TRUNK LINE HEADER**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>D</i>	<i>1</i>	<i>17S</i>	<i>34E</i>					<i>LEA</i>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	<i>TRUNK LINE</i>	Volume of Release	<i>100 BBL</i>	Volume Recovered	<i>35 BBL</i>
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	<i>12/28/09</i>
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	<i>OCD - SHERIDAN</i>	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
*N/A*

Describe Cause of Problem and Remedial Action Taken.\*  
*COLD WEATHER, POLY LINE BUSTED - VACUUM TRUCK & GANG AT ONCE ON SITE REPAIR & CLEANUP DONE.*

Describe Area Affected and Cleanup Action Taken.\*  
*VACUUM TRUCK & GANG CLEANED UP & REPAIRED LINE - WE DUG OUT BAD TOP SOIL & CATCHES GRAYED OFF BAD SOIL & REPLACED WITH GOOD CATCHES & TOP SOIL. & RESEED.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Keith Henson</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	<i>Keith Henson</i>	Approved by: ENV ENGINEER:	<i>Jeffrey J. J. J.</i>
Title:	<i>Lease Operator</i>	Approval Date:	<i>03/24/10</i>
E-mail Address:		Expiration Date:	<i>-</i>
Date:	<i>3-23-2010</i>	Conditions of Approval:	<input type="checkbox"/> Attached
Phone:	<i>432-260-9637</i>	<i>IRP-09-12-2369</i>	

\* Attach Additional Sheets If Necessary