

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 100 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	MC Federal #37	Facility Type	Oil Pump

Surface Owner	Federal	Mineral Owner		Lease No.	30-025-39108
---------------	---------	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	21	17S	32E	870	South	1600	West	Eddy LEA

Latitude N32 48.926' Longitude W 103 46.495'

NATURE OF RELEASE

Type of Release- Oil	Volume of Release-55 bbls	Volume Recovered- 45 bbls
Source of Release- Wellhead	Date and Hour of Occurrence- 12/13/09	Date and Hour of Discovery 12/13/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Trishia Bad Bear, Larry Johnson, Jeff Leaking	
By Whom? Pat Ellis	Date and Hour 12/14/09 1:18pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.*

The wellhead packing had blown out. We have replaced packing.



Describe Area Affected and Cleanup Action Taken.*

Most of the fluid remained on the pad. About 5 to 10 bbls rolled off the pad on the west side of the location. We scraped the pad and hauled off contaminated soil.

Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor 	
Printed Name: Kanicia Carrillo	ENVIRONMENTAL ENGINEER	
Title: Regulatory Analyst	Approval Date: 3.31.10	Expiration Date: 5.31.10
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval:	
Date: 12/28/09 Phone: 432-685-4332	Submitted Final C-141 & Docs 34 Attached <input type="checkbox"/> IRP# 10.3.2467	

* Attach Additional Sheets If Necessary