State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back / side of form

Lease No 300252638500

Release Notification and Corrective Action

OI	PERATOR	Initial Report	Final Report
Name of Company ConocoPhillips Company	Contact John W. Gates		
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158		
Facility Name EVGSAU Well# 2913-006	Facility Type Oil and Gas		

Surface Owner State Of New Mexico

LOCATION OF RELEASE

Mineral Owner State Of New Mexico

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	29	175	35E					
						<u> </u>		

Latitude

Longitude

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered		
Crude Oil & Produced Water	10.3bbl (3oil, 7.3water)	(3oil, 7water)		
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery		
Hole in a 2 7/8" steel surface flow line	3/14/10 12:00 pm	3/14/10 12:30 pm		
Was Immediate Notice Given?	If YES, To Whom?			
🗋 Yes 🔲 No 🖾 Not Required				
By Whom?	Date and Hour	, , , , , , , , , , , , , , , , , , ,		
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	e.		
🗌 Yes 🖾 No				
If a Watercourse was Impacted, Describe Fully.*				
	WATER 965			
Describe Cause of Problem and Remedial Action Taken.*	101110-0140			
Release originated from a hole in a 27/8" steele surface flow line due to suspected internal/external corrosion. A vacuum truck				
picked up 3 bbls of crude oil and 7 bbls of produced water. The spill site will be remediated in accordance with an agreement with				
NMOCD.				
Describe Area Affected and Cleanup Action Taken.*				

Affected area is a 35' X 20' X .5'' area od dry, hard, caliche road and pad. A vacuum truck picked up 3 bbls of crude oil and 7 bbls of produced water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

	OIL CONSERVATION DIVISION
Signature:	ENV ENGINEER:
Printed Name: John W. Gates	Approved by District Supervisor: HEERRALL SolomE
Title: HSER Lead	Approval Date: 05/12/10 Expiration Date: 07/12/10
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: SUBMIT FINAL Attached
Date: 3/16/10 Phone: 505.391.3158	C-141 BY 07/12/10 RP-10-5-2522
A COLLARD AND A TOTAL AND A TONTA AND A COLLARD AND A	

Attach Additional Sheets If Necessary