

District I
1025 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services L.P.	Contact: James Lignau 505.394.2534, Chuck Tolson 505.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice Gas Plant	Facility Type

Surface Owner: TARGA RESOURCES	Mineral Owner:	Lease No.
--------------------------------	----------------	-----------

LOCATION OF RELEASE API # 30-025-21497-00-00

Unit Letter	Section 3	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.25.16.9N Longitude 103.08.47.8W

NATURE OF RELEASE

Type of Release: Gas and Produced Liquids	Volume of Release: Approximately 20 barrels of liquid	Volume Recovered: Recovered approximately 20 barrels of liquid.
Source of Release: Dresser Sleeve separated on dump line from Separator in plant condensate handling area.	Date and Hour of Occurrence: 12 Midnight 7/29/2008	Date and Hour of Discovery 12 Midnight 7/29/2008
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson OCD in Hobbs by phone	
By Whom? Don Embrey	Date and Hour: 11:30 AM 7/29/2008	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Pig pushed maximum amount of liquid into separator and caused overpressure of dump line and dresser sleeve on line separated. Liquid was contained in containment around separator and clean up excavation. Drip truck was called out and liquid recovered. Line was shut in and dresser sleeve repaired.

Describe Area Affected and Cleanup Action Taken.*

The liquid was contained in containment and clean up excavation. Track hoe brought in to remove contaminated soil in bottom of excavation. The contaminated soil will be taken to an OCD approved landfill. The area will be sampled to insure cleanup to meet OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	ENVIRONMENTAL Approved by District Supervisor: 	
Title: Advisor	Approval Date: 06/08/10	Expiration Date: 08/09/10
E-mail Address: dembrey@targaresources.com	Conditions of Approval: SUBMIT FINAL C-141 BY 08/09/10	Attached <input type="checkbox"/> IRP-10-6-2554
Date: July 29, 2008 Phone: (432) 688-0546		

* Attach Additional Sheets If Necessary