

RECEIVED

JUN 22 2010

HOBBSOCD

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	<i>Ranger 40</i>	Contact	<i>Alan Standefer</i>
Address	<i>1004 Giller Center Way Suite #208</i>	Telephone No.	<i>505-557-8722</i>
Facility Name	<i>LJTA #89</i>	Facility Type	<i>Injection Line</i>
Surface Owner	Mineral Owner		Lease No. <i>#89</i>

LOCATION OF RELEASE API # 30.025 W 630.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>H</i>	<i>17</i>	<i>25S</i>	<i>37E</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>Lea</i>

Latitude *—* Longitude *—*

NATURE OF RELEASE

Type of Release	<i>Produced water</i>	Volume of Release	<i>20 BBL</i>	Volume Recovered	<i>0</i>
Source of Release	<i>Injection Line</i>	Date and Hour of Occurrence	<i>6.7</i>	Date and Hour of Discovery	<i>6.8</i>
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	<i>11:00 am</i>	<i>8:30 am</i>	
By Whom?	<i>Jacobs Melancon</i>	Date and Hour	<i>Tommy Thompson 1 OCA</i>		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<i>0</i>		

If a Watercourse was Impacted, Describe Fully.*

none

WATER @ 80'

Describe Cause of Problem and Remedial Action Taken.*

Injection line blew out causing produced water to travel south in pasture following line to #92 location - Plan to scrape and haul area then grab initial samples on site

Describe Area Affected and Cleanup Action Taken.*

Pasture south of location approximately 10-13' wide followed line south to #92 location - Scrape pasture and haul off to disposal

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature	<i>Alan Standefer</i>			OIL CONSERVATION DIVISION	
Printed Name	<i>Alan Standefer</i>			ENV. ENGR : Approved by District Supervisor: <i>Jeff Labine</i>	
Title	<i>Contract Pumper</i>			Approval Date: <i>06/30/10</i>	Expiration Date: <i>08/30/10</i>
E-mail Address				Conditions of Approval: <i>SUBMIT FINAL C-141 BY 08/30/10.</i>	Attached <input type="checkbox"/>
Date:	Phone:			<i>IRP-10-6-2573</i>	

* Attach Additional Sheets If Necessary