

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

JUN 25 2010

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 25 2010

HOBBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Samson Resources Company	Contact: Autumn Long
Address: Two West Second Street	Telephone No. (918) 591-1364
Facility Name: Minis 2 R Fed #1	Facility Type: Injection Well (W)

Surface Owner:	Mineral Owner:	Lease No.: 6202296
----------------	----------------	--------------------

LOCATION OF RELEASE

30-025-34449-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	2	T21S	R32E	360	South	660	East	Lea

Latitude: 32.50123 Longitude: -103.63839

NATURE OF RELEASE

GW @ 140'

Type of Release: Produced Water	Volume of Release: 45 Barrels	Volume Recovered: 35 Barrels
Source of Release: Water Valve Load Line	Date and Hour of Occurrence: 6/21/2010; Unknown.	Date and Hour of Discovery: 6/21/2010; 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoff Leking - District 1 (505) 393-6161 (6/21/2010 at 4:00 p.m.) Terry Gregston - BLM Carlsbad Office (575) 234-5972 (6/21/2010 at 4:05 p.m.)	
By Whom? Autumn Long	Date and Hour: 6/21/2010 4:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Contract water hauler left water valve handle on load line and did not close valve at tank; cow rubbed valve open; releasing 45 barrels of produced water; all fluid remained on location. Remedial action included all standing fluids, approximately 35 barrels, were vacuumed-up; backhoe picked-up impacted soil, down to caliche, and properly disposed of impacted soil.

Describe Area Affected and Cleanup Action Taken.*

All fluids remained on location; Length: 140' Width: 4'8' Depth: 2'
Remedial action included all standing fluids, approximately 35 barrels, were vacuumed-up; backhoe picked-up impacted soil, down to caliche, and properly disposed of impacted soil. Confirmation sampling of soil to occur 6/23/2010; to be witnessed by Bureau of Land Management representative.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Autumn M. Long</i>	OIL CONSERVATION DIVISION	
Printed Name: Autumn Long	ENV. ENGR Approved by District Supervisor: <i>Jeffrey Shinsky</i>	
Title: Associate Environmental Specialist	Approval Date: 07/07/10	Expiration Date: 09/07/10
E-mail Address: autumnl@samson.com	Conditions of Approval: SUBMIT FINAL C-141 BY 09/07/10	Attached <input type="checkbox"/> 10-7-2574
Date: June 22, 2010 Phone: (918) 591-1364		

* Attach Additional Sheets If Necessary



Samson

Samson Plaza
Two West Second Street
Tulsa, Oklahoma 74103-3103
USA
918/591-1791

SENT VIA CERTIFIED MAIL

June 22, 2010

State of New Mexico Energy Minerals and Natural Resources
District 1
Attn: Geoff Leking
1625 N. French Drive
Hobbs, NM 88240

RECEIVED
JUN 25 2010
HOBBSOCD

Reference: Release Notification and Corrective Action
Operator: Samson Resources Company
Location: Minis 2 R Fed #1
Section 2, T21S-R32E
Lea County, NM

Dear Mr. Leking:

Per the initial telephone notification to you on 6/21/2010 at 4:00 p.m., and to Terry Gregston with BLM at 4:05 p.m., please find attached a completed Form C-141 regarding the above referenced release.

Please recognize it is Samson's intent to operate in an environmentally responsible manner and to maintain compliance with applicable laws and regulations. I trust this information will satisfy any concerns the State of New Mexico Energy Minerals and Natural Resources and Bureau of Land Management may have regarding this incident. If you need additional information, please feel free to contact me at (918) 591-1364.

Thank you.

Sincerely,

Samson Resources Company

Autumn M. Long

Autumn Long
Environmental Specialist
db:

Attachments

Cc: Bureau of Land Management
Carlsbad Field
Attn: Terry Gregston
620 E. Greene Street
Carlsbad, NM 88220

Gerry Petree – Superintendent
Production Department