

RECEIVED

AUG 30 2010

Form C-141

Revised October 10, 2003

NMOCD ARTESIA

Copies to appropriate District Office in accordance with Rule 116 on back side of form

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

30-015-32151

## Release Notification and Corrective Action

nmlb103452817

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Antelope SWD 8" Lateral Line	Facility Type	8" SWD Line

Surface Owner	State	Mineral Owner	Lease No. B-3627
---------------	-------	---------------	------------------

Antelope St #3

## LOCATION OF RELEASE

Unit Letter K	Section 36	Township 17S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 47.503

Longitude 103 49.432

## NATURE OF RELEASE

Type of Release Produced water		Volume of Release 80bbls	Volume Recovered 0bbls
Source of Release 8" SWD lateral line		Date and Hour of Occurrence 08/17/2010	Date and Hour of Discovery 08/17/2010 3:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		If YES, To Whom? Mike Bratcher—OCD	
By Whom? Josh Russo		Date and Hour 08/17/2010 10:06 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A 10' section of the 8" SWD line became uncovered and exposed to weather which weakened the pipe causing it to rupture. The ruptured section of the pipe has been removed and replaced with new pipe.

Describe Area Affected and Cleanup Action Taken.\*

Initially 80bbls of produced water was released from the 8" SWD line and we were unable to recover any fluid due to the location of the release and the absorption rate of the sand. The dimensions of the release area is 12' x 90'. (The release site is 100 yards north of the Antelope State #3 well location, 2310' FSL 2310' FWL, Sec.36-T17S-R-31E, Eddy Co., NM, B-3627, AP# 30-015-32151). Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Josh Russo		Signed By:  Approved by District Supervisor:	
Title: HSE Coordinator		Approval Date: NOV 10 2010 Expiration Date:	
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:	
Date: 08/30/2010 Phone: 432-212-2399		Attached <input type="checkbox"/> REMEDATION per OCD Rules and	

\* Attach Additional Sheets If Necessary

2RP-477

①

**Bratcher, Mike, EMNRD**

---

**From:** Joshua Russo [jrusso@conchoresources.com]  
**Sent:** Monday, August 30, 2010 9:13 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Pat Ellis; Tavarez, Ike  
**Subject:** C-141 - Antelope SWD 8" Lateral Line (08/17/2010)  
**Attachments:** ANTELOPE SWD 8 INCH LATERAL LINE -- DATE OF RELEASE -- 08172010.PDF

Mr. Bratcher,

Please see attached the C-141 Initial Report for the Antelope SWD 8" line release that occurred on 08/17/2010.

Thank you,

**Joshua Russo**

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.